American Machinist

[ISSUED WEEKLY]

The International Journal of the Machinery Industries

Volume 72
January 2 to June 26, 1930

McGraw-Hill Publishing Company, Inc.
Tenth Avenue at 36th Street
New York

American Machinist

Index to Volume 72

January 2 to June 26, 1930

	Page
Jan. 2	1-38
Jan. 9	39-77
Jan. 16	78-168
Jan. 23	169-206
Jan. 30	207-244
Feb. 6	245-282
Feb. 13	283-320
Feb. 20	321-358
Feb. 27	359-396
Mar. 6	397-434
Mar. 13	435-472
Mar. 20	473-510
Mar. 27	511-548
Apr. 3	549-604
Apr. 10	605-642
Apr. 17	643-678
Apr. 24	679-714
May 1	715-752
May 8	753-788
May 15	789-824
May 22	825-860
May 29	861-898
June 5	899-936
June 12	937-974
June 19	975-1012
June 26	1013-1050

A

"A-S-E" all-steel tool cabinets *895
"A-S-E" all steel tool chest *969
"A-S-E" stacking boxes *897

Accidents and Accident Prevention:

Chip shields for the turret lathe. Chas. H. Willey *311
Conference method in safety work 521
Making safety rules, and enforcing them. Leslie Childs 257
Safety campaign that achieved results. Edwin W. Thomas 217
Safety device for presses. D. C. Bailey *999
Safety helps to build financial independence. M. Phillips 882
Safety sign for ladders. T. Kruger .. 831
Safety tool for the press operator. A. R. Kling *310
Safety tool for the press operator. A. Raymond 925
Accounting—Determining the when and why of machine tool replacement. J. R. Weaver 1013
Acme turret lathe for tungsten carbide .. *1007
Acyclic generator for tube welders *746
"Ads," using blind 248
"Ads," using blind ads. W. Lestye.—Discussion 514
"Ads," using blind. P. H. Pearson.—Discussion 611
"Ads," using blind. L. F. Swenson 735
Adams manufacturing hobbers *935
Adapter for holding non-magnetic metals. C. T. Whitehouse *925
Adapter for universal indicator. H. Ball .. *962
"Advance" grinding and lapping machine .. *502
Air cleaner, Hammond motor *634
Airbrush, Paasche multicolor *707

Aircraft Construction:

Automobile methods influence plane interiors (N) 434a
Allen-Bradley automatic pressure switch . *673
Allen-Bradley single-phase starting switch . *547
Allis-Chalmers tractors produced by all modern equipment. William Watson *436

Alloys:

Aluminum alloys for pistons and cylinder heads. A. J. Lyon 996
"Duronze" silicon-bronze alloy 1005
Phosphor-copper for welding and brazing. C. J. Snyder *793
"P. M. G." metal—a hardened copper alloy 709
Westinghouse "phos-copper" welding alloys 860
For threaded parts. J. D. Porter 762
Fusion welding of aluminum (Ref. Book Sheet) 885
Fusion welding of aluminum (Ref. Book Sheet) 927
Nickel plate on aluminum 409
Not aluminous 57
Zinc plating aluminum parts to prevent seizing 363

Aluminum:

American Broach and Machine Co.—Hydraulic broaching press *237
American Foundrymen's Association—First regional meeting 548c
American Iron & Steel Institute—It's the long pull (ed) 854
American Road Builders Association—Convention and exposition 206c

American Society of Mechanical Engineers:

Commemoration and re-dedication ... *643
Fiftieth anniversary celebration (N) .. 434a
Fiftieth anniversary tablet *642a
Genesis and evolution: short history of the society *551
Ames dial micrometer *281
Anderson mill-type grease pump *708
Angle irons. Chas. H. Willey *232
Angle plate, adjustable. A. Feucht *852
Apex friction chuck *890

Apprentices:

Apprenticeship courses for seniors. John A. Masek 484
Co-operation in vocational education. R. F. Carey 697
Just what is an apprentice?—Discussion. A. W. Forbes 774
Just what is an apprentice? C. V. Freund *181
Training by intention. G. Guy Via. *725, 773
Arbor—expansion arbor. O. C. Parham .. *538
Armstrong tool holders for tungsten-carbide bits *1048
Ashdown "Rotoscope" *971

Assembling Machines:

Fabrication and assembly of Goldy Seals *286
Associations — federation of machinery associations (ed) 350
Auburn end-thrust ball bearing *710
Aulenback wrenchless boring tools (ed) *35
Automatic Machine Co.—diamond boring a motor end shield bearing *640

Automobiles—Manufacture:

Assembling American cars in Japan. Fred H. Colvin *522
Bonderizing and enameling as practices by Chrysler. H. Chase *755
Comment on American passenger-car gear sets. H. Chase *909
Die-pressed parts reduce production costs. H. Chase *835
Dies and tools for four-piece rear-axle housings. Frank W. Curtis .. *219
Ford body assembly at Chester plant. H. Chase 1021
Ford stock and traffic control. G. E. Hagemann *975
From nine-inch slab to welded motor frame *682
High spots in the Pierce-Arrow cylinder line. Fred H. Colvin *4
Murray unit finishes and trims 900 bodies a day. C. W. Avery *476
Nash "8" connecting rods in production. Frank J. Oliver, Jr. ... *291, 332
Nash fuel tank covers determined by experiment. Frank J. Oliver, Jr. .. *172
Selective inspection cuts assembly costs. W. G. Holmes 806
Stamping and assembling 100 Murray bodies an hour. C. W. Avery *397
Steering 6,400 steering gears through manufacture. J. B. Nealey *519
Studebake transmission cases production *367
Tooling for 250 pistons an hour. Frank W. Curtis *489
Weatherproofing winterfronts. F. J. Oliver, Jr. *830
Wedge dies solve Nash press job. Frank J. Oliver, Jr. *253
Welded automobile bodies and the oxy-acetylene torch. Joseph W. Meadowcroft 521
"Autostart" model 1930 grinder *319
Avey texdrive sensitive drill *316

B

Babbitt pot—Trent electric *888
Babbitting—As a positive operation. C. B. Lord *937
Baird chucking machine *824
Baker-Case machinists' chests *807
Balancing machines, review of *121
Ball with two grooves at right angles. G. Wilson *921
Bandsaw, metal-cutting with hydraulic feed *1041
Barnes automatic lathe *743
Hydaulic vertical honing machine *235
Medium-heavy-duty honing machine .. *503
Bars, round bars as machine guides 681
Bastian-Blessing Co. — Rego "Economizer" shut-off for welding gases *205
"Rego" welding torch *202

Bausch and Lomb:

Optical bevel protractor *507
Optical centering level *543
Optical comparator *508
Shop microscope *749
Bays, high and low. John R. Godfrey 346
Beading machine, Niagara *509

Bearings:

Accurate bearings. John R. Godfrey 346
Auburn end-thrust ball bearing *710
Maintenance of motor bearings. D. R. Hammitt 775
Beeswax for self-equalizing fixtures. D. A. Baker *666
Bellevue electric furnace for heat treating *239
Bellevue industrial electric soldering iron heater *431
Bellevue toolroom furnace *897
Belt guards 323

Belts:

Care of planer belts. W. E. Warner. 946
Chart for finding belt lengths (Ref. Book Sheet) 467
Dive for Adams gear hobber and thread miller *935
Guards should be sturdy but not too bulky 829
Making endless belts. A. V. O'Brien. *813
Benches—Two drawers in benches.—Discussion 657
Bending and curling tool. James R. Cornelius *273
Bending—Fixture for coils. C. H. Willey. *924
Fixture, for copper and brass tubing. J. J. Roethlisberger *883
And jeweling fixture. C. H. Willey .. *777
And straightening machine. Thomas. *431
"Bent Hole." W. F. Cain *498
Besly double-spindle grinder *1042
Betts car wheel borer *856
Horizontal boring, drilling, and milling machine *352
Biax "Supra" flexible-shaft machines *279
Bicycles—How small Japanese shops build bicycle parts. F. H. Colvin *846
Bins, Simplex nesting *1007
Blanks—Nash fuel tank covers determined by experiment. Frank J. Oliver, Jr.. *172
Bliss double-crank presses *887
Double-eccentric high-production press *627
High-production press with scrap shear *471
Blount grinder for tungsten carbide tools. *934
Blower and vacuum cleaner—"U. S." *711
"Blue diamond" high speed drills 889
Blueprinting and Blueprints—Ready-made sketches for the toolroom. C. W. Hinman *195
Bohnalite housings on "U. S." tools *545
Boilers—"Old man" for boiler front ends. F. H. Colvin *849
Bolendar gear burnisher *784
Gear burnisher *1049
Gear grinding chuck *872
Model 0 gear burnisher *782
Bolts—Removing by stretching them. P. H. White 681

Book Reviews:

Airplane mechanics rigging handbook. S. Hartz and Elzor E. Hall 444
Applied mechanics. A. T. Poorman .. 959
Arithmetic of electricity. T. O'Connor Sloane 685
Audit of America. Edward E. Hunt. 729
Balancing of engines. W. R. Dalby .. 444
Blueprint reading 264
Conditional sales. Roger Sherman Hoar 264
Thomas Davenport. Walter Rice Davenport 444
Electroplating with chromium, copper and nickel. Benj. Feeman and F. G. Hoppe 663
Examination of earnings in certain standard machine tool occupations in Philadelphia. H. L. Fraln 663
Factory organization and management. R. C. Davis 685

(*) Illustrated (‡) Diagram (ed) Editorial

620.5 v.72 pt.1

Page

Forty years with General Electric. John T. Broderick ... 190
General metal work . A. B. Grayshon. 981
History of wages in the U. S. from colonial times to 1928. U. S. Dept. of Labor ... 264
[illegible]iness management. [illegible]kwell.....294, 663
[illegible] in the United States. Norman J. Ware ... 294
MacRae's Blue Book and Hendicks Commecial Register ... 294
Market data handbook of the U. S. Paul W. Stewart ... 264
Die Maschinenelemente. Friedrich Barth ... 264
Material control and storeskeeping in machine shop and foundries. Willis Wisler ... 444
Materials handling equipment. E. J. Tournier ... 866
Mechanical tightening. L. E. Noble and J. A. Roenick ... 418
"Mechanical World" electrical pocket book ... 959
"Mechanical World" year book for 1930 ... 866
Modern aviation engines. Major Victor Page ... 218
National organization and industrial relations ... 981
Pickling of iron and steel. W. G. Imhoff ... 685
Proceedings of the 17th Annual Convention of the American Railway Tool Foreman's Association ... 729
Progress towards legal recognition of a precise inch standard. Amer. Inst. of Weights and Measures ... 218
Psychology for executives. Elliot D. Smith ... 663
Repesentative international cartels, combines and trusts ... 190
S. A. E. Handbook ... 866
Scientific management in American Industry ... 663
Standards year book, 1930 ... 981
Steel treating practice. Ralph H. Sherry ... 294
Successful control of profits. W. Rautenstrauch ... 959
Technique of executive control. Erwin H. Schell ... 729
Robert Henry Thurston. Wm. Fredrick Durant ... 418
Wage incentive methods. Chas. W. Lytle ... 190
Welding encyclopedia (ed) Mackenzie & Card ... 959
Work routing in production. John Younger ... 685

Boring:

Betts car-wheel borer ... *856
Betts horizontal boring, drilling and milling machine ... *352
Boring and turning machines (review number) ... *79, 80
Concavities and convexities ... *420
Davis cylinder boring head ... *541
Diamond boring an aviation articulated rod ... *395
Diamond boring a motor end shield bearing ... *640
Diamond boring shock absorber housing ... *712
Finding clearance for work on boring mills. W. R. Needham ... 701
Fixture for boring piston-pin holes. Geo. Wilson ... *311
Head for milling machine. H. F. Crawford ... *999
Jig boring machine, Hauser No. 2 ... *73
Mill of unlimited capacity ... *953
Precision boring in a vertical milling machine. M. Bidwell ... *921
Quick-change boring heads. G. W. Hammitt ... *922
Universal "Tri-way" hoizontal machine ... *354
Wrenchless boring tools, Aulenback (E) ... *35
Boston light-duty speed reducers ... *675
Boxes—Stacking ... *897
Bradford drilling and reaming machine ... *243

Brakes:

Handling air-brake parts in a Japanese shop. F. H. Colvin ... *813
Brass—Hot-pressed brass parts production. H. Chase ... *879
Brazing—Phosphor-copper for welding and brazing. C. J. Snyder ... *793
Breur industrial vacuum cleaner ... *710
Brickner-Kropf adjustable toolroom lap ... *239
Bridgeport buffing lathes ... *892
Broaches, supporting the outer ends. D. R. Hammitt ... *702
Broaching machine — Ironing out tapered tubes. L. L. Locke ... *777

Brown & Sharpe:

Automatic rod magazine for automatic screw machine ... *972
Automatic screw threading machines ... *970
Depth gage attachment ... *390
Depth gages Nos. 614, 617 ... *37
Fulfilling replacement promises. K. H. Condit ... 789
Railway car wheel gages ... *675
Redesigned plain milling machine ... *238
Standard screw gage ... *677
Telescoping gages ... *390
Buffalo billet shear ... *855
Twin "Breezofin" unit heater ... *969
Universal shears ... *968
Wrapping rolls ... *352

Page

Buffing wheel, "Quick-as-wink" ... *1008
Buhr horizontal, high-speed drilling machine ... *505
Hydraulic-feed, multi-head drilling machine ... *428
Sliding-arm drilling and tapping heads ... *543
"Super" drilling and boring machine. *277
Bullard-Dunn electro chemical cleaning process ... *633
Bulldozer, 75-ton "American" ... *73
Burnisher—"Bolendar" gear ... *1049
Bolendar gear burnisher ... *784
Bolendar model 0 gear burnisher ... *782
Crown motor-driven machine ... *1043
Burs, Keller mill-cut ... *974
Bushings—"Universal" nitralloy bushings. 821

Business Conditions:

Need for regional economic councils at the New England Council ... *249
Outwitting the business cycle (ed) .. 198
Business ethics. — Discussion. P. Ford Smith ... 306
Bussman high-pressure pumps ... *971

C

Cable and wire testing machine, Olsen *75
Caliper, "United" dial ... *351
Cam roller fitted with roller bearing. Peter A. Brill ... *231
Cams—Three-dimension fixture for cutting cams. C. W. Hinman ... *270
Carrier vapor degreaser for impervious materials ... *74
Carter detachable rim wheel for bandsaws. *890
Case, hardening practice for tractor gears. J. Fletcher Harper ... *449
Casters-Saginaw Parkerized ball-bearing ... *472

Castings:

Completely mechanized foundry for tractor castings. E. A. Harrison .. *445
Die-casting today. M. Stern ... *1029
Heavy castings and special machines. H. W. Liebert ... 453
"Cataract" motor-driven bench lathe *1045
Century totally inclosed fan-cooled motors. *542
Chains—Link-Belt "Hyper" ... *750
Transue & Williams conveyor chain .. *1043
Chambersburg motor-driven head for board drop hammers ... *200
Chamfering machine—Lipe flywheel ring gear ... *858
Chicago "Little Giant" pneumatic grinder and buffer ... *205
China as a machine market. F. H. Colvin. *945

Chucking Machines:

Air-operated chuck. B. J. Stern ... 537
Apex friction ... *890
Baird chucking machine ... *824
Bolender gear grinding chuck ... *672
"Ettco" portable drill chuck ... *241
Extensions for chuck jaws. Henry Mansfield ... 348
For turning valve rings. H. P. Leonard ... *229
Hannifin four-jaw duplex pneumatic chuck ... *891
"Titan" safety drive chuck ... *1043
Turning valve rings. J. G. Turton *629
Westcott drill chuck ... *1045
Cincinnati—Bickford radial drill ... *786
Bickford radial drill ... *936
Cam-controlled planer produces smooth contours ... *357
Centerless grinder ... *713
Cutter grinder with face mill grinding attachment ... *635
"Hydromatic" for milling crankcase front cover ... *394
"Hydromatic" miller for bottle molds. *394
"Hydromatic" milling machine ... *783
"Hypro" planer-type miller ... *317
Miller ... *787
Miller with ferris wheel fixture ... *640
Plain "Hydromatic" miller with an indexing base ... *356
Plain and swivel vises ... *387
Plain and universal milling machines .. *748
Planer has grinder head ... *353
Press brake ... *893
Roll honing attachment for grinders .. *823
Semi-automatic plunge cut grinder ... *31
Universal gages for press brakes .. *891
"Cipco" polishing and buffing machine *817
Clamp—Improved tool clamp. Joseph Villiger ... *194
For micrometer extension rods. F. S. Doughty ... *630
Quick-acting device. L. O. Brown 228
Clamping fixtures — Fitted to T-slots. Theodore Kruger ... *272
"Clarostat" soldering-iron heat controller. *1010
Cleaning, electro chemical—Bullard-Dunn .. *633
Ryerson sand-blase flue system ... *636
Clough grinding attachment for engine lathes ... *320
Clutch—Johnson "super clutch" ... 428
Coats Machine Tool Co.—"Mikrotast" tap lead tester ... *204
"Mikrotast" wire tester ... *201
Cocks—making tight plug-cocks ... 312
Coils—Making flat, from copper wire. Charles H. Willey ... 64
"Colorgraph" box strapping ... 507
Colvin, Fred H., honored by Japanese engineers ... *781
Comparator—Bausch & Lomb optical *536
"Comtorplug" model comparator ... *892

Page

Compressor—Gardner-Denver "A-C-E" *320
"Comtorplug" model comparator ... *892
Concavities and convexities ... *379, 419
Concavities, convexities and ovals ... *463
Condit across-the-line starters ... *471
Air motor starter ... *638

Connecting Rods:

Nash "8" connecting rods in production. Frank J. Oliver, Jr. .. *291, 332
Controllers—For low-head cranes, General Electric ... *36

Controls:

General Electric crane and hoist controls ... *390
"Wright" dynamic, lowering-circuit controller for crane hoists ... *282

Conveying and Conveyors:

Dip-the-dip conveyors ... *195
Hevi duty floating-belt-type conveyor furnace ... *547
Semi-portable conveyors in tractor production. Chester B. Lord ... *215
Thirty-five minutes per carload. R. H. Lucke ... *993
Coolant — What coolant shall we use? Chester B. Lord ... 407
What coolant shall we use? Discussion W. H. Oldacre ... 771
Coring—Combined core drill and countersink ... *740

Costs:

Costing for profit. A. E. Grover ... 899
Executive interest in. Thomas B. Frank ... 50
Facts for financiers (ed) ... 424
Simple checking system to reduce excess cost. G. W. Dunham ... 844
Wages not chief factor in machine economy (ed) ... 276
Coulter—Diamond borner used on aviation articulated rod ... *395
Double-spindle diamond boring machine ... *712
Countersinking machine—Kent double nut. *1046
Coupling—"Quick-as-wink" valve coupling. *818
Spring Flexible. Chas. Kugler ... *739
Spring flexible—discussion. J. T. Towlson ... 382
Morse flexible ... *280
Cranes — Gantry-type Cleveland tramrail cranes ... *626
Crankshaft—133 ton crankshaft ... 714g
Credit—What are your terms? ... 795
Crossheads—Mold for relining laird-type. J. H. Hahn ... *848
Set-ups for machining. Geo. H. Feltner ... *465
Crown motor-driven burnishing machine .. *1043
Crown overhanging type polishing lathe ... *747
Cullman improved speed reducer ... *673
Cutler-Hammer—Overload switch for small motors ... *392
Small pressure regulator ... *752
Cut-off machine, "Radiac" ... *819
Cutter wedges, safety clamp for Ernest Foldvary ... *312

Cutters:

Centralizing gear cutters. Chas. Kugler ... *702
DeWalt heavy-duty timber ... *240
"Geweco" automatic shape cutter ... *677
Landis grooving cutters for "Victualic" joints ... *932
Stanley-Unishear metal cutting tools .. *711
Wells cutter sharpener ... *1010

Cutting:

Armor plate ordeal for tungsten-carbide. Henry A. Ingram ... *39
Automatic oxy-acetylene, shape cutting machines made to cut smoothly 700
Oxygen cutting of steel, wrought iron, and cast iron. F. E. Rogers ... 191
Balancing cutting-tool costs (ed) 1002
Cutting fluids—What coolant shall we use? C. B. Lord ... 407
What coolant shall we use? Discussion W. H. Oldacre ... 771

D

Davenport five-spindle screw machine *705
Davis cylinder boring head ... *541
Expansion reamer ... *671
Defiance special drilling machine ... *393

Design:

Of stand type jigs. J. A. Potter *62
Practical contact for the designer.—Discussion. W. B. Needham ... 457
Shortening labor in design calculations.—Discussion. E. Manning ... 491
Despatch indirect gas-fired oven ... *432
DeVlieg "Supermil" ... *745
De Walt acquires Wodack electric handsaw ... *709
Heavy-duty timber cutter ... *240
Dial plate with adjustable nests. C. G. Foreman ... *1033
Diamonds—Industrial. (Ref. Book Sheet) .. *283
Diamond "type H" universal-head surface grinding machine ... *32
Die spotting machine—Nahquette ... *639
Diehead—"Landex" internally tripped ... *1040

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Modern self-opening *896
"Namco" revolving-type opening die-head *782
Rickert-Shafer self-opening *894

Dies:

Die-casting today. M. Stern *1029
Die-pressed parts reduce production costs. H. Chase *835
Die that was a failure. D. A. Baker. *1036
Positive knock-out for progressive dies. C. G. Foresman *999
Producto die sets *355
Roller-type bending die *738
Slitting die.—Discussion. C. A. Coppack 193
Typical standard die sets (Ref. Book Sheets) 539, 853
"U. S." standardized die sets..... *1008
Wedge dies solve Nash press job. Frank J. Oliver, Jr. *253
Dogs—Driving work by three. H. Moore.. *1000
Drafting—Recording changes on drawings. W. R. Needham..... 344

Drawing:

Accuracy and speed in detailing. Geo. H. Gunn 466
Accuracy and speed in detailing.—Discussion. W. R. Needham..... 1035
Colored inks for clarity. Morton Schwam 193
Colored inks for drawing clarity.—Discussion. W. R. Needham 775
Improvement in draftsmen's triangles. G. A. Luers *998
Preventing blanks from slipping. F. J. Cawley *230
Production for draftsmen's scales. H. S. Steele *851
Reproducing drawings to a different scale. G. W. McArd 271

Drilling:

Accurate drilling of small holes.—Discussion. W. C. Betz..... *813
Accurate drilling of small holes. C. Kugler *232
Accurate drilling of small holes.—Discussion. J. T. Towlson..... 925
Keeping step in drilling *761
Kink for the drillers. J. T. Towlson. 810
Landau drilling and tapping machine.. *750
Special machines for producing straight 8-cylinder blocks for Pierce-Arrow cars. Fred H. Colvin .*4
Speeding attachment. I. F. Yeoman .*849

Drilling Machines:

"Blue diamond" high-speed drills... 889
Buhr horizontal, high-speed drilling machine *505
Buhr hydraulic-feed, multi-head machine *428
Buhr sliding-arm drilling and tapping heads *543
Buhr "super" drilling and boring.... *277
Cincinnati Bickford radial drill..... *936
Cincinnati Bickford radial drill..... *786
Defiance special machines *393
Drill-press table has false tops. D. D. Vandercook *193
"Express" high-speed drilling machine. *893
"Gen-rad" and "Hy-rad" radial drills. *425
"Hercules" pneumatic on portable stand *392
Hisey-Wolf radial stand with sensitive feed *282
Jigs for drilling and reaming. Standard Die & Tool Co. *515
Kingsbury drilling and tapping machine *787
Kingsbury three-heat automatic..... *243
Langelier duplex machine *821
Langelier semi-automatic 5-way machine *357
Langelier semi-automatic upright.... *638
Texdrive sensitive drill *316
"U. S." electric drills with improved chuck spindles *503
Western "low-hung-drive" radial drills. *506

Drills and Drilling:

Adjustable multi-spindle drill head. R. E. McCoy *65
Drilling machines (review number). *81-88
"Hercules" drill for high-manganese steel *1050
Pneumatically actuated jigs for. R. E. McCoy *55
Drive wheels, welding. Frank J. Oliver, Jr. *11
"Durimit" floor surfacing material 505
"Duronze" silicon-bronze alloy 1005

E

"E. C. & M." type NT master switch.... *639
"Economy" automatic double-end turning machine *973
Automatic pointing machine..... *973
Eddystone approaches completion..... *874
Efficiency—How much? W. R. Needham. 1025
How much? W. F. Schaphorst 61
Electrical equipment, review of..... *122, 125
Electrode holder—Wache metallic *712
"Electrolene"—Substitute for industrial hydrogen 674
Elwood toggle-type reel lifter and stand. *1050

Page

Employees:

According to the rules (ed) 540
Dismissal wage (ed) 816
Foreman training lags (ed) 780
Human engineering (ed) 670
Productive occupations for industrial veterans (ed) *473
Responsibility (ed) 966
Slow but not so sure 475
Spend the machine and spare the man (ed) 772
Stop gaps for leaky payrolls..... 535
Straightening the employment curve. W. B. Lincoln, Jr. 763
Trend of employment in metal-working industries 206c
What happens to the engineer..... 307

Enamel and Enameling:

Bonderizing and enameling as practiced by Chrysler. H. Chase *755
Do's and don'ts in vitreous enameling. C. D. Clawson *947
Pickling for vitreous enamel. C. D. Clawson *295
Weatherproofing winterfronts. F. H. Oliver, Jr. *830

Engineers:

Ceremonial raiment for engineers (ed) 704
Indication of progress (ed) 886
June crop (ed) 670
Tomorrow's executives (ed) 1038
What happens to the engineers..... 307

Engineering:

Reliable source of information..... 267
Role of engineering education. D. S. Kimball *575
Engraving machine—"Simplex" *859
Equalization of clamps—Use beeswax. D. A. Baker *666

Equipment:

An act of faith in modern equipment. Otto H. Falk 435
All-modern equipment produces Allis-Chalmers Tractors. William Watson *436
Fulfilling replacement promises. K. H. Condit 789
How much obsolete equipment are you using? (ed) 350
Semi-annual review of *77, 168d
Semi-annual shop equipment review—corrections 282
"Esico" industrial electric soldering irons. *281
"Ettco" portable drill chuck *241
Europa—Machine shop extraordinary to the "Queen of the Seas." E. J. Tangerman *799

Executive Forum:

Does reciprocity pay?..... 832
Inspection or discretion? 1018
Is budgetary control a cure-all?..... 212
Is the customer always right?..... 686
Is incentive necessary?..... 758
Jigs by whom?..... 906
Other fellows toes 982
Pensions or leaky payrolls?..... 650
Ratio of raw materials to production 8
Sales or sincerity? 288
Should estimates be given operatives? 44
Should overhead be uniform?..... 612
Should price or payroll be cut?..... 364
Should salesmen design?..... 480
Should small shops co-operate?..... 868
Should special work be segregated?.. 328
Should spending be influenced?..... 796
Success or successor?..... 942
To whom should the chief inspector report? 174
What price titles?..... 250
Who should control routing?..... 402
Who should do the firing?..... 516
Why an organization chart?..... 720
Exhibitions—Excessive entertainment at exhibitions (ed) 928
Exhibits and exhibitions (ed) 886
Experience—Is it a handicap?..... 424

Exports:

Assaying the export market. Geo. R. Woods *283
Eleven months machinery exports for 1929 ..... 206a
Europe also exports. F. M. Mansfield 664
Europe's electro-technical industries survey their export markets. Francis Miltoun 396c
Machinery exports for 1929. L. J. Cochrane 282a
Navigation in overseas markets (ed).. 30
Our changing exports. S. R. March. 736
Place of exporting in planned prosperity.—Discussion 772
Place of exporting in planned prosperity. W. H. Rastall 169
Sales across the seas 605
What price exports (ed) 742
"Express" high-speed drilling machine.... *893

F

Falk right-angle drive *277
Fatigue testers—Smallest and largest.... *642c
Federal open-back punch presses..... *890
Files—"Profilo" ball files *1009
Filing machine—Rausch die *708
Finishing—Storing and mixing *618
Fitchburg Grinding Machine Corp.—"Bath" motor-driven universal grinder *203

Page

Fixtures:

Bending fixture for a small part. Chas. H. Willey *466
For checking keyways. Chas. Kugler. *422
For holding a cylinder block while end is milled. Standard Die & Tool Co.. *515
For milling the water inlet elbows for cylinder blocks. Standard Tool & Die Co. *485
High-speed graduating. G. E. Jacobson *850
Welding fixtures arc-welded *188
Flather geared-head engine lathe..... *1039
Flexible shaft machine—Biax "Supra".... *279
Floor liner Nissly *674
Floor plan of the Allis-Chalmers tractor plant 478
Floor surfacing material "Durimit"..... 505
Ford Motor Co.—Ford body assembly at Chester plant. H. Chase 1021
Ford stock and traffic control. G. E. Hagemann *975
Foreman—Good foremen a world-wide need (ed) 70

Foreman's Round Table

Boss, or advisor? 524
Chain store problem 620
Closing the door to late comers 336
Experience or authority?..... 914
Foremen and the wage bonus..... 410
Government work 730
High rates 802
Honest graft 990
Keeping machines on the job..... 184
Material handling 876
Mottoes in the shop 258
New drills and old men 16
No verbal orders accepted 658
Off with the old on with the new.. 222
Old kinks and new ideas 372
Quality or quantity?..... 768
Safety court 950
Spring song 694
Too much co-operation 52
Vacations again 840
When personal tools are damaged.... 486
Why conferences, anyway?..... 298
Wrong number 1026

Forging:

Hot-pressed brass parts production. H. Chase *879
Nazel motor-driven forging hammer.. *504
Foster—Duplex turret lathe *1044
"Fastermatic" turret lathe *1004
Special crank turning machine..... *242

Foundry:

Completely mechanized foundry for tractor castings. E. A. Harrison.. *445
General Steel Castings Corp.—being built *678f
What of the foundry? C. B. Lord... *679
Four-corner flash welder Taylor-Winfield.. *201

France:

Industrial situation 244c
Metal industries short of labor 358c
Free silver and false prophets (ed)..... 70
Frequency converter—Reliance *894
Frew horizontal two-spindle profiling machine *280
Frew vertical two-spindle profiling machine *278

Furnaces:

Bellevue electric for heat treating.. *239
Bellevue toolroom furnace..... *897
Despatch indirect gas-fired ovens.... *432
Hevi duty floating-belt-type conveyor furnace *547
Hevi duty Nitriding furnace *1010
Hevi duty rotary retort furnace..... *749
"Hydro" automatic industrial furnaces *929
Overcoming the smoking habit in oil-fired furnaces. F. J. Gutsch..... *417
Trent electric furnace *858
And equipment, review of..... *125
Future, Auguries of—Electrical World. L. W. W. Morrow 602
Engineering and Mining Journal. Arthur Allen 603
Electronics. O. H. Caldwell 603
American Machinist. K. H. Condit.. 603
Power. Ely C. Hutchinson 601
Aviation. Edw. P. Warner..... 601
Engineering News-Record. F. E. Schmitt 601
Textile World. Douglas G. Woolf.... 602
Chemical and Metallurgical Engineering. S. D. Kirkpatrick..... 603

G

Gages and Gaging:

Accuracy in angle gaging. J. A. Potter *1024
American gage design standards (Ref. Book Sheet) 1001
Ammonia-treated gage steel. A. J. Wormwood 452
Brown & Sharpe depth gage attachment *390
Brown & Sharpe railway car wheel gages *675

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Brown & Sharpe standard screw gage. *677
Brown & Sharpe telescoping *390
Checking outlines on contour gages. Chester H. Franklin *422
Cincinnati universal gages for press brakes *891
Constant-center Vee Blocks. H. Moore. *811
Depth, for measuring liquids. Elton Sterritt *25
Depth, Nos. 614 and 617, Brown & Sharpe (ed) *37
For checking tapers. Ernest Foldvary. *383
Gaging three-fluted taps. N. N. Sawin *963
Indicating gage for roll retainers. H. J. Stern *383
Large height gage. Dr. H. Goldschmidt *923
Lip clearance gage. A. P. Gwiazdowski *838
Lufkin radius gages *896
Machines, review of *121
One certain surface gage. Fred Rebmann *653
Selective inspection cuts assembly costs. W. G. Holmes 806
Simple flush-pin gages. W. N. Delenk *1034
Starrett cutter clearance gage *934
Gardner-Denver "A-C-E" compressor *320
Garvin heavy-duty automatic tapping machine *353
Gas—"Electrolene," substitute for industrial hydrogen 674
Gasket compound—"Nacotex" 471
Gaskets—Combination die for making lead gaskets. L. L. Locke *812

Gears and Gearing:

Case-hardening practice for tractor gears. J. Fletcher Harper *449
Comment on American passenger-car gearsets. H. Chase *909
Constant chord gaging. W. A. J. Chapman *753
Cutting a double-thread workwheel with a single-thread hob.—Discussion. J. Thomas 776
Cutting a double-thread wormwheel with a single-thread hob. Chas. B. Irmer 232
Finding centers of new teeth in a repaired gear. H. Moore *812
Gear cutting and testing machines (review number) *88, 90
"Hammar" gear tooth form *1047
Holding starter gears for tooth rounding. I. B. Rich *850
National-Cleveland gear checking machines *434
Reinecker bevel gear generators *635
Support for gears in a hobbing machine. C. Cornwall *1035
33,000 steel spur gear (N) *860d
Westinghouse gear unit for driving rolls in steel mill *676
Gellert automatic safety tongs *34

General Electric Company:

Automatic welding electrode feeding device *200
Controller for low head cranes (ed) .. *36
Crane and hoist controls *390
Magnetic reversing switch *747
Photo-electric relay *751

Generators:

Acyclic generators for tube welders .. *746
Frame and hub for Spier Falls generator *678c
"Gen-rad" and "Hy-rad" radial drills *425
Gerstner tool chest *897
"Geweco" automatic shape cutter *677
Gisholt—Turret lathe *641
Turret lathe with rolling-in valve seats 712
Globe automatic tapping machine *351
Golden Anniversary number 549
Gouger-Putnam square billet gouger *544
Gray "Super" universal tapping attachment *320
Greenfield "Pericles" screw plates *1049
Greenfield reamers *1046
Gridley four spindle automatic *781

Grinders:

Adapter for a grinder. J. H. Boyd .. *668
"Advance" grinding and lapping machine *502
"Autostart" model 1930 ..... *319
"Bath" motor-driven universal *203
Bench-type, Wappat "Red Streak" ... *75
Besly double-spindle grinder *1042
Blount grinder for tungsten-carbide tools *934
Chicago "Little Giant" pneumatic grinder and buffer *205
Cincinnati centerless grinder *713
Cincinnati cutter grinder with face mill grinding attachment *635
Combination disk and production, Hammond (ed) *36
Clough attachment for engine lathes .. *320
Diesel engine crankshaft bearings—grinder *641
Fixture for an odd-shaped casting. F. J. Oliver, Jr. *228
Grinding machines (review number) *91, 98
Hammond bench type electric grinder. *859
Hammond double disk grinders *472
Hammond grinder and buffer *973
Haskins toolpost *205
Heald internal grinder *785
"Hercules" portable grinder *1049
"Hercules" portable pneumatic grinder. *784

Page

"Hercules" sander and cup wheel grinder *352
"Hisey" disk and floor stand grinder .. *509
Jarecki internal and face grinder *235
"Jewel" die and tool grinder *510
"Kripp" air grinder *277
Landis hydraulic roll grinders *199
National-Cleveland spur and helical gear grinding machine *433
Norton roll grinder *818
Olofson precision *204
"One profit" pedestal grinder *972
Pratt & Whitney hydraulic gear grinder *1006
Ransom heavy-duty *239
Ransom heavy-duty *280
Ransom snagging wheel guards *711
Reinecker automatic indexing hob and tool grinder *857
Rivett integral slide-rest grinder *896
Roll honing attachment for Cincinnati grinders *823
Rotary pneumatic, "Thor" *74
Semi-automatic plunge cut, Cincinnati *31
Simple cam grinding fixture. E. Delbridge *961
"Standard" high-speed snagging grinder *707
"Standard" tungsten carbide grinder. *1007
Surface grinding machine, Diamond type H universal-head (E) *32
Wells drill grinder *541
Wells round cutter grinder *548
Turret-type internal and external, Rivett No. 104-5 ..... *71

Grinding:

Device for testing the grinding of hobs. E. E. Keeler *629
Device for grinding work that is not straight. Carl G. Alt *384
Fixture. H. F. Fiedler *778
Tungsten-carbide tools (Ref. Book Sheet) 965
Wet grinding 654
Gun, Temple used to set threaded studs .. *245
"Gyro" coolant pump *970

H

Hacksaw blades and some of their uses. Wm. S. Rowell *536
Hall production hone *545
"Hammar" gear tooth form *1047
Hammer—"Stanley-Ajax" electric hammer. *509
Hammers—Chambersburg motor-driven head on board drop hammer *200
Hammerman in the Orient 681
"Quickwork" twin power hammer ... *1005
Hammond—Bench type electric grinder .. *859
Combination disk and production ... *36
Double disk grinders *472
Grinder and buffer *973
Motor air cleaner *634
"Handnib" nibbler and rod cutter *546
Hannifin four-jaw duplex pneumatic chuck. *891

Hardness:

Hardness by "cloudburst." E. G. Herbert *917
Indicating hardening temperature by sale. Emil Stumpp 497
Shore hardness indicator *1050
Haskins type HL-5 toolpost grinder *205
Hauser No. 28 jig boring machine *73
Headers—Manville high-speed convertible double or single headers *429
Heald Machine Co.—Internal grinder *785

Heat Treatment:

Cyclic heat-treating of motorcycle parts. S. B. Phillips *1032
Despatch indirect gas-fired ovens *432
Economics and economies of heat-treating. Robert M. Keeney *225
Heat-treating job shop organized along modern lines. Frank J. Oliver, Jr. *375
Practical heat-treating in the small shop. Arthur Mumper *690
Practice in manufacturing caterpillar tractor parts *22
Heaters—Bellevue industrial electric soldering iron heater *431
Buffalo twin "Breezofin" unit *969
"Heliocentric" and "Revocentric" speed reducers *546
"Hercules" — Drill for high-manganese steel *1050
Pneumatic drill on portable stand .. *392
Portable grinder *1049
Portable pneumatic grinders *784
Right-angle nut driver *1048
Sander and cup wheel grinder *352
Hevi duty — Floating-belt-type conveyor furnace *547
Nitriding furnace *1010
Rotary retort furnace *749
Hisey—Buffer and polisher *857
Disk and floor stand grinder *509
Hisey-Wolf radial drilling stand with sensitive feed *282
Hobbers—Adams manufacturing *935

Hoists:

Electric, Robbins & Myers *32
Mathews "Pullift" hoist *673
Providing lifting devices on machine tools. T. Addison *902
Holder for knurling and cut-off tools. Jack Ferris *25

Page

Hone-Hall production hone *545
Honing machines—Barnes hydraulic vertical *235
Barnes medium-heavy-duty honing machine *503
Hoover medal (ed) 704
Hopkins arbor press *933
Horse—"Toledo" steel *822
Hose protector. Frank C. Hudson *466
Housings—Dies and tools for four-piece rear-axle housings. Frank W. Curtis *219
Huff expansion reamer *895
"Hydro" automatic industrial furnaces *929
"Hydromatic" milling machine *242
"Hydro-power" press *501

I

"Ideal" speed lathe for polishing operations *508

Industry:

Business outlook for 1930. Gerard Swope (N) 38b
Climbing cycles of industrial production. Alvan T. Simons 10
Good faith and good business (ed) ... 780
Review of, in 1929. Robert P. Lamont (N) 76a
Will nineteen thirty be as good as nineteen twenty-nine? K. H. Condit .. 1
Inspection—Practice of caterpillar tractor parts *22
Simple checking system to reduce excess cost. G. W. Dunham 844
Installment buying of machinery (ed) 314
International mind (ed) 424

Iron:

Factors affecting machinability of malleable cast iron. H. A. Schwartz 871
Important developments in the gray-iron industry. Arthur J. Tuscany .. 415
Inventory time (ed) 500

J

James spiral-bevel-gear right-angle speed reducer *677

Japan:

Also builds electrical machinery. F. H. Colvin *764
As a market for American machinery. Fred H. Colvin 268
Assembling American cars in Japan. Fred H. Colvin *522
Bicycles and lubrication; shoes or sandals; one-man shops 617
Building machine tools and locomotives in Osaka. Fred H. Colvin *648
Has set a precedent for the next World Engineering Congress. Fred H. Colvin 378
How small Japanese shops build bicycle parts. F. H. Colvin 846
Jigs in Japan. Fred H. Colvin *495
Lubrication in Japan—tools upside down 920
Scheduling locomotive repairs. Fred H. Colvin *207
Jarecki internal and face grinding *235
"Jewel" die and tool grinder *510

Jigs and Fixtures:

Adjustable jig. C. R. Whitehouse *884
Correcting errors in jig work. Chas. Kugler 498
Double fixture for milling plier parts. H. C. Francis *24
Drill jig. Arthur V. O'Brien *738
Drill jig built up by welding. George H. Feltner *28
Jig for center drilling. Theodore Kruger *739
Jig for drilling holes in mica. H. N. Kirk *465
Jig for receiving and chamfering brackets. Standard Tool & Die Co. *485
Jigs in Japan. Fred H. Colvin *495
Planning and design of stand type jigs. J. A. Potter *62
Pneumatically actuated drill jigs. R. E. McCoy *55
Special machines for producing straight eight-cylinder blocks for Pierce-Arrow cars. Fred H. Colvin *4
Student jig design. A. P. Gwiazdowski. *923
Wedge-operated V-block. Albert Feucht *776
Jointer, Wallace hand *672

K

"Kant-slip" apron feed mechanisms on Bradford lathes *930
Kearney & Trecker—Miller with rotary fixtures *356
Special head for milling locating pads on tractor blocks *393

(*) Illustrated (‡) Diagram (ed) Editorial

Page

"Keldur" vibration-insulating and sound proofing material 783
Keller mill-cut burs *974
Kent—Bolt and stud pointing machine..*821
Double-nut-countersinking machine..*1046
Kent-Owens heavy-duty milling machines.*1003
Kingsbury drilling and tapping machine..*787
Three-heat automatic drilling machine.*243
"Kleenkut" shear knives 392
Klopp crank-type shapers *931

L

Labor:

France finds metal industries short of labor 358c
It's all in the approach (ed)..... 500
Labor-saving and labor-making (ed).. 468
Protection for industrial veterans.... 615
Review of certain wage systems. James R. Cornelius 342
Laidlaw metal-cutting bandsaw with hydraulic feed *1041
Lamps for inspecting small holes. H. James *926
Landau drilling and tapping machine.....*750
"Landex" internally tripped diehead....*1040
Landis—Bolt threader and former.....*933
Grooving cutters for "victualic" joints *932
Hydraulic roll grinders.....*199
Langelier—Automatic taper pin swaging machine *318
Duplex drilling machine.....*821
Semi-automatic 5-way drilling machine *357
Semi-automatic for machining watch stems *787
Semi-automatic upright drilling machine *638
Spoke swaging machine.....*430
Lapping Machine—"B-K" adjustable toolroom lap *239
"Modern" tungsten-carbide lapping machines *967
LaSalle Machine Works Inc.—"Version" all-steel press *204

Lathes:

Acme turret lathe for tungsten carbide *1007
Barnes automatic lathe.....*743
Bench lathe of unusual design.....*654
Bridgeport buffing lathes.....*892
"Cataract" motor-driven bench lathe.*1045
Chip shields for the turret lathe. Chas. H. Willey.....*311
Concavities and convexities.....*379
Crown overhanging type polishing lathe *747
18-inch manufacturing. Lodge and Shipley *33
Equipment in review number.....*99, 102
Flather geared-head engine lathe....*1039
Foster duplex turret lathe.....*1044
Foster "Fastermatic" turret lathe...*1004
Gisholt turret lathe.....*641
"Ideal" speed lathe for polishing operations *508
"Kant-slip" apron feed mechanisms on Bradford lathes *930
LeBlond automatic crankshaft lathes.*469
Monarch standardized flanged spindle.*819
"Newark" worm grinding attachment for engine lathes.....*319
Production turning on an engine lathe. Ernest Foldvary *196
Reed-Prentice high-speed, sliding-gear-head *388
Reed-Prentice sliding-gear-head lathes.*750
Rivett speed box motor drive for bench lathes *820
Rolling-in valve seats on Gisholt turret lathe *712
Sebastian "Gold seal" heavy duty lathe *541
South Bend metric engine lathes....*433
South Bend "New model" lathe.....*672
South Bend 9-in. precision.....*240
Truing felt rolls in the lathe. W. B. Lincoln, Jr. 997

Law:

As applied to industry. Herbert Braasch 345
Laying out table. F. S. Doughty.....*667
LeBlond automatic crankshaft lathes.....*469
Leckie elevating die truck.....*472
Level—Bausch & Lomb optical centering level *543
Levers—Locking lever for a jig. C. W. Hinman *231
Lincoln—Automatic welder for cross brake shafts *639
Automatic wire wheel welder.....*205
"Lightweld" welding rod..... 892
"Stainweld A" welding rod..... 746
Link-Belt "Hyper" chain.....*750
Link-Belt Timken pillow block.....*1047
Lipe flywheel ring gear chamfering machine *858
Live center—Sturdimatic roller bearing...*708
Lockwashers—Reliance stainless steel..... 710

Locomotives:

Air-operated clamp for holding hub liners. C. W. Frank.....*814
Eddystone approaches completion....*874
How one shop reconditions locomotive superheaters. J. O. B. Palmer....*405
Locomotive springs in process. H. P. Leonard *340

Page

Planing crossheads of. J. H. Hahn..*67
Reclaiming locomotive crossheads. J. H. Hahn *628
Repairing locomotives in a university shop in Mukden. F. H. Colvin....*791
Scheduling locomotive repairs in a Japanese shop discussion. W. Bryce 905
Scheduling repairs in a Japanese shop. Fred H. Colvin.....*207
Welding drive wheels for. Frank J. Oliver, Jr. *11
Lodge and Shipley 18-inch manufacturing lathe (ed) *33
Loshbough-Jordan open-back inclinable press *1009
Louden motor-driven trolley.....*895

Lubrication:

Lubrication of ball and roller bearings. (Ref. Book Sheet)..... 499
Nathan mechanical lubricators.....*1048
Norgren air line lubricator.....*1048
What coolant shall we use? Chester B. Lord 407
Lufkin radius gages.....*896

M

McKinney—Type "C" rolling machine....*389
Type "B" rolling machine.....*387

Machinery:

Determining the when and why of machine tool replacement. J. R. Weaver 1013
Fulfilling replacement promises. K. H. Condit 789
Installment buying (ed)..... 314
Is this slander? (ed)..... 500
Japan also builds electrical machinery. F. H. Colvin.....*764
Japan as a market for American machinery. Fred. H. Colvin..... 268
Langelier semi-automatic for machining watch stems.....*787
New—from the ground up (ed)..... 468
New high-speed machine tools (ed).. 928
Should the machinery industries speak with one voice? (ed)..... 70
Suggestions, complaints, and progress (ed) 276
Too much machinery (ed)..... 966
Tooling for typesetters. R. R. Mead..*825
Wanted—a soda-proof finish (ed).... 742
What if the Soviet's machine gods fall down? Whiting Williams.....*321
What is normal operation in the machine tool industry? E. F. DuBrul..*960
"Maco" adjustable template.....*860

Management:

American management methods in a European car shop. Wallace Clark.*511
Analyzing the high executive (ed)... 314
By exception. Chester B. Lord..... 308

Mandrel:

Flanging splash pans on the lathe. Reinhold Koch *231
For turning splined gear blanks. H. L. Wheeler *230

Manufacturers:

Aiding the manufacturer to make repairs. W. F. Schaphorst..... 757
Index to, listed in semi-annual review number 143
Manville Screw trimmer.....*671
High-speed, convertible double or single-stroke headers *429
Marking Machines—Noble & Westbrook improved production marking machine *237
Marquette cushioned press bed.....*675
Die spotting machine.....*639
Riveting machine *676
"Marvel" Nos. 6 and 6A high-speed hack sawing machines *34

Materials:

Engineering materials analyses. (Ref. Book Sheet) *69
Irons, steels and alloys.....*139
"Keldur" vibration-insulating and sound-proofing material 783
Tube and bar weight charts. (Ref. Bk. Sheets) 815

Materials Handling:

Review of equipment.....*126
Matthews "Pullift" hoist.....*673
Measurements—use persists (ed)..... 198

Measuring Devices:

Formula for measuring dovetails. Clarke B. Heath.....*272
Making and using a sine-bar. R. M. Gamble 811
Measurement conversion tables. (Ref. Book Sheet) 1037
Metal Working—Trend of employment in the industry (Ch).....282c

Metals:

Detecting cracks in metal articles. W. E. Warner..... 814
Determining the shrinkage of liquid metal in cooling..... 346

Page

Longer-lived equipment for pickling. C. A. Crawford *58
Nickels and monel metal. (Ref. Book Sheet) 385
Phosphor-copper for welding and brazing. C. H. Snyder.....*793
Pickling. (Ref. Book Sheet)..... 313
Pre-finishing treatments for metal surfaces. (Ref. Book Sheet)..... 423
Spark testing of metals. (Ref. Book Sheet) 703
Uncommon properties of a common metal. Robert M. Curts.....*413
Mexico (ed) 966
Micro-indicator stand, Société Genevoise...*706
Indicator tube, Société Genevoise.....*239
Micrometers—Ames dial.....*281
Microscope—Bausch & Lomb.....*794
Milling—Vise with hold-down jaws. H. E. Brookman *28

Milling Machines:

Betts horizontal boring, drilling and milling machine *352
Brown & Sharpe redesigned plain....*238
Cam-operated milling fixture. Arthur Mumper *701
Cincinnati "Hydromatic" for milling crankcase front cover.....*394
Cincinnati "Hydromatic" milling machines *783
Cincinnati "Hydromatic" miller for bottle molds *394
Cincinnati "hypro" planer-type.....*317
Cincinnati miller *787
Cincinnati plain "Hydromatic" miller with an indexing base.....*356
Cincinnati plain and universal.....*748
Cutting helical grooves in a case-iron roll. G. W. Kehres.....*851
Cutting steam ports in cylinder bushings. M. H. Westbrook.....*273
Device for milling locomotive quadrants. Max Schwarze *310
DeVlieg "Supermil" *745
Feeler blocks on milling fixtures. C. W. Hinman *1036
Ferris wheel fixture on Cincinnati duplex miller *640
Head for milling locating pads on tractor blocks *393
"Hydromatic" *242
Indexing type milling fixture. Standard Tool and Die Co.....*485
Kent-Owens heavy-duty milling machines *1003
Milling ports in a valve bushing. Max Schwarze *273
"Milwaukee" machines with two-spindle head *395
"Mil-Waukee-Mil" *241
"Mil-Waukee-Mil Simplex" rough milling grinder beds.....*786
Reed-Prentice die sinker and miller....*392
Review of *103, 105
Rotary fixture on Kearney and Trecker Miller *356
Set-up for milling machines. R. H. Kasper *630
Simplified binding device. J. Kopp...*852
Spline milling cutters. Fred A. Firnhaber *177
Stamets automatic spline milling machine *542
Sundstrand rigidmil *236
Turntable of a boring mill.....*244c
Wells thread milling machine.....*710
"Milwaukee" Milling machines with two-spindle head *395
"Mil-Waukee-Mil" milling machine.....*241
Splitting bearing caps on connecting rods *823
Simplex—rough milling grinder beds..*786
Modern self-opening diehead.....*896
"Modern" tungsten-carbide lapping machines *967
Mohr & Federstaff Brinell hardness tester.*1009
Molding machines. Terkelsen.....*507
Monarch standardized flanged spindle.....*819
Morse flexible couplings.....*280
Morton—Attachment for shaping locomotive stoker discharge boxes.....*713
Crosshead planing attachment.....*894
Draw-cut shaper *889
Draw-cut shaper for machining cast-steel hub *394
Motion pictures used for transmitting information between plants (ed).... 670
Motions, Mechanical — Management tool (ed) 1002
Motor-generator, Reliance *317

Motors:

Century totally inclosed fan-cooled motors *542
Insight into outboards. H. B. Kilroe.*689
Smoothing the power load.....*324
Westinghouse carriage driving unit...*968
"Multimechanic" *888

N

"Nacotex" gasket compound..... 471
Namco revolving-type opening dieheads...*782
Nathan mechanical lubricators.....*1048
National Assn. of Cotton Mfgrs.—the first stone (ed) 854
National Assn. of Engine & Boat Mfgrs.—Exhibition 244a

(*) Illustrated (‡) Diagram (ed) Editorial

Page

National Business Survey Conference:
Begins stabilization work (N) 38a
Meeting to survey progress in readjustment 206a
National—Cleveland gear checking machine *424
Spur and helical gear grinding machine *433
National Management Congress 472c
National Metal Trades Assn.—Plans for convention 510a
Nazel motor-driven forging hammer *504
Niagara beading machine *509
Niagara press *891
Nissly floor liner *674
Noble & Westbrook production marking machine *237
Norgren air line lubricator *1048
Norton roll grinder *818
Nut driver—"Hercules" right-angle *1048
Nuts—Dimensions of recessed pockets for nuts—discussions. W. R. Needham. *274
Tool for facing large nuts. J. H. Hahn *777

O

Obsolescence — What obsolete equipment costs *715
Ohio "Super-dreadnaught" railroad shaper. *1011
Olsen, Thorsten Y., succeeds father (N) ... *38c
"One profit" pedestal grinder *972
Orders, specifications for customers. C. H. Wiley 619
Oster pipe reamer *823
Pipe threading machine *817
Three-way pipe threader *898
Williams threader and reamer for small pipe *970
Oxweld portable testing machine *858
Steel welding rod 431
Welding blowpipe *471
Oxygen cutting of steel, wrought iron, and cast iron. F. E. Rogers 191

P

Paasche "Hudson" production striper *969
Multicolor airbrush *707
Spraying unit with silencer *932
Tank and gun for spraying body noise deadening compound (ed) *36
Paint Sprayer—Paasche unit with silencer. *932
Painting equipment, review of *127
Palmer-Edwards Co. — Olofson precision grinder *204
"Palmgren" adjustable machine vise *1048
Parts—charging for spare parts (ed) 816
Peening retaining rings with air hammers. C. H. French *740
Photo-electric cell—As a safety device (ed) 704
Pickling, longer-lived equipment for metal. C. A. Crawford *58
Metal. (Ref. Book Sheet) 313
Pillow block—Link-Belt Timken *1047
Pipes, preventing soap streaks when painting. Joe Kelly 628

Pistons:
Finishing Ford to specified weight ... *751
Tooling for 250 pistons an hour. Frank W. Curtis *489
Planer stop. H. L. Wheeler *271
Planers—Cincinnati cam-controlled planer produces smooth contours *357
Grinding head for Cincinnati planer. *353
And shapers, review of *106
Planing—Fixture for planing circular grooves. H. L. Wheeler *776
Planing locomotive crossheads. J. H. Hahn *67
Morton crosshead planing attachment *894
Plates—Improving index. J. Ellis *1036
Straightening iron plates 312
Trimming machine *733

Plating:
Precision plating through timed equipment. G. W. Gammons *492
Wanted—Satisfactory tests for cadmium plating correction 263
Plug cocks—Making tight. J. G. Turton .. 963
Pointing machine—"Economy" *973
Kent bolt and stud *821

Polishing and Buffing:
"Cipco" machine *817
Equipment, review of *127
Hisey buffer and polisher *857
Porter-cable "Speedmatic" saw *709
Pratt & Whitney—Hydraulic gear grinder. *1006
Pre-finishing treatments for metal surfaces (Ref. Book Sheet) 423
President's final word to industry (ed) .. 30

Press:
American hydraulic broaching press .. *237
Automatic delivery mechanism for. B. J. Stern *66
Automatic feed rolls for a punch press. Norman McKay *347
Bliss double-crank presses *887
Bliss double eccentric high production. *637
Bliss high-production press with scrap shear *471
Cincinnati press brake *893
Double-acting tools for a press. C. W. Hinman *961
Federal open-back inclinable punch presses *890
400-ton crank press. Toledo Machine & Tool Co 548
Guards—Good and bad. E. J. Clarke 700
Hopkins arbor press *933
H-P-M-"Hydro-power" presses. Hydraulic Press Mfg. *501
Improvised hot press. C. R. Whitehouse *1035
Improvised rubber spring for the drawing press. Chas. H. Willey *383
Losbough-Jordan open-back inclinable press *1009
Magazine feed for a punch. A. R. Kling *24
Niagara press *891
Review of *108
Simplex "Utility" *279
Toledo crank press *634
Tools for ammeter covers *192
Tools for ammeter covers. S. Fortune 999
"Version" all-steel press *204
Verson straight-side steel-frame *391
Zeh & Hahnemann percussion power press *747
Zeh & Hahnemann pillar toggle presses *889
Press bed—Marquette cushioned *675

Production:
All-modern equipment produces Allis-Chalmers tractors. William Watson. *436
American management methods in a European car shop. Wallace Clark. *511
Climbing cycles of industrial. Alvan T. Simonds 10
Increased, with dual and multiple tooling. F. H. Mayoh *19
Insight into outboards. H. B. Kilroe. *689
Plus incentive to high production. F. Trevor Daniel 661
Semi-portable conveyors in tractor production. Chester B. Lord *215
Special-purpose equipment for accurate tractor parts. Frank J. Oliver, Jr.. *458
Tooling for high production over a long period. H. P. Leonard *367
Producto die sets *355
Profiling machines—Frew horizontal two-spindle *280
Frew vertical two-spindle *278
"Profilo" ball files *1009
Prosser grinding gage for tungsten-carbide tools *707
Protractor—Bausch & Lomb optical bevel. *507
Puller for gears and couplings. H. J. Burnham *997

Pumps:
Anderson mill-type grease pump *708
Bussman high-pressure pumps *971
"Gyro" coolant pump *970
"Rotapiston" pump *856
Ruthman vertical coolant pump *637
Wayside pumps in process *655

Punches:
Cross-keys for holding heavy punches. Ernest Foldvary *194
Cross-keys for holding heavy punches. —Discussion. F. C. Twist *538
For cloth-inserted packing rings. C. C. Tomney *1000
Hand, for sheet metal. P. H. White .. 64
Hand-operated screw punch. P. H. White *195
Punching and shearing machines, review of *110
Punching shells for light sockets. S. B. Kraut *497
Putty—"Weldite" filler *1042
Putnam square biller gouger *544

Q

"Quick-as-wink" rubber cushioned buffing wheel *1008
"Quick-as-wink" valve coupling *818
"Quickwork" twin power hammer *1005

R

Racine hydraulic power saw *744
Racks, storage, for layout boards. O. J. Franklin *26
"Radiac" cut-off machine *819

Railroads:
American management methods in a European car shop. Wallace Clark. *511
Inspection and repair of tactographs. Chester B. Lord *527
More views from a European car shop. *724
Need of railway shop equipment (ed) 632
Odds and ends in a railroad shop. H. P. Leonard *261
Rack made from discarded parts. C. W. Frank *668
Railway tools in a Canadian shop. F. W. Curtis *977
Renewing wheel flanges of trolley cars. *305
Ranson heavy-duty grinder *280
Heavy-duty grinder *239
Snagging wheel guards *711
Rausch rotary die filing machine *708
Ray type electric screw driver *391
Type electric screw driver *504

Reamers and Reaming:
Bradford drilling and reaming machine *243
Davis expansion reamer *671
Greenfield reamers *1046
Huff expansion reamer *895
Oster pipe reamer *823
"Oster-Williams" threader and reamer for small pipe *970
Reaming in the lathe. C. R. Whitehouse *629
Reaming taper holes to a given depth. G. J. Miller *740
Reed-Prentice die sinker and miller *392
High-speed, sliding gear-head lathe .. *388
Sliding gear-head lathes *760
Reel lifter, Elwood toggle-type *1050
Regional council, another (ed) 1002
Regulator—Cutler-Hammer small pressure. *752
"Weldit" multi-stag *432
Reinecker automatic indexing hob and tool grinder *857
Bevel gear generators *635
Relay—General Electric photo-electric relay *751
Reliance frequency converters *894
Motor-generator *317
Stainless steel lockwashers 710
Remote control for Stephens-Adamson speed changer *72

Research:
Machine tool 1015
Support for machine tool research. John Edwards 462
Support for machine tool research.—Discussion. E. F. DuBrul 757
Support for machine tool research.—Discussion. J. Edwards 837
Rickert-Shafer self-opening diehead *894

Rivets and Riveting:
Marquette riveting machine *676
Ways and means of riveting the sub-assemblies for calculating machines. Frank W. Curtis *343
Rivett integral slide-rest grinder *896
No. 104-5 turret-type internal and external grinder *71
Speed box motor drive for bench lathes *820
Robbins & Myers electric hoists *32
Rockford hydraulic planer-shaper with side head *969
Rogers—Circular saw sharpener *202
"Quad 4-in-1" hacksaw *279

Rolling Machines:
McKinney type "B" *387
McKinney type "C" *389
Machine for rolling circles from strip. B. J. Stern *271
Rolling mill—Steel strip at half a mile a minute *941
"Rotapiston" pump *856
Rotary forming. C. V. Lundeen *912
Rotation—Device for intermittent. E. Kilburn *925
"Rotoscope"—Ashdown *971

Russia:
Politics, business or religion? (ed) .. 386
What if the Soviet's machine gods fall down? Whiting Williams *321
What of the U. S. S. R.? (ed) 780
Rust remover. C. E. Whitehouse 976
Ruthman vertical coolant pump *637
Ryerson "New Haven" sand-blast flue cleaning system *636

S

Safety device for handling press work. B. J. Stern *27
Safety tongs, Gellert automatic *34
Saginaw Parkerized ball-bearing casters. *472

Sales:
If laid end to end (ed) 540
What are your terms? 795

Saws and Sawing:
De Walt acquires Wodack electric handsaw *709
Disston—One of the world's largest metal-cutting *282b
Hacksawing machines, "Marvel" Nos. 6 and 6A high-speed *34
Machines, review of *114, 115
Portable electric saws, "Speedway" types 183, 184 ..... *71
Porter—cable "Speedmatic" saw *709
Racine hydraulic power saw *744
Rogers "Quad 4-in-1" hacksaw *279
Stanley-Crowe safety saw *544
Van Dorn portable electric saw *677

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Screwdrivers—Power. Chas. R. Whitehouse 384
Ray type electric *391
Screw driving machine, Ray type *504
Screw-machine — Davenport five-spindle screw machine *705

Screws:
Assembling small screws and nuts. Chas. H. Willey *196
Extending the travel of a screw. A. Fontanella *849
Greenfield "Pericles" screw plates *1049
Half turn for holding work.—Discussion. V. Van Zeebroeck *274
Setting of threaded studs by means of the Temple Gun. Chester B. Lord. *245
Scribe block for toolmakers.—Discussion. Rudolph Keil 66
Seals, Goldy—Fabrication and assembly. *286
Sebastian "Gold seal" heavy-duty lathe. *541
Selective assembly (ed) 1038

Shafts:
Flexible shaft possibilities. J. E. Hyler 839
Strand flexible-shaft machine *752
Using tumbling barrel shaft to agitate washing basker. Chester H. Franklin *194

Shaper:
Gooseneck tool for the shaper.—Discussion. R. B. Ware 629
Gooseneck toolholder for the shaper.—Discussion. Thomas Fish *630
Klopp crank-type shapers *931
Morton attachment for shaping locomotive stoker discharge boxes *713
Morton draw-cut shaper *889
Morton draw-cut shaper for machining cast-steel hub *394
Ohio "Super-dreadnaught" railroad shaper *1011
Problem in shaper work. A. R. Klingman *229
Problem in shaper work.—Discussion. D. R. Dunstone 312
Problem in shaper work.—Discussion. A. J. Pruszynski *924
Problem in shaper work.—Discussion. S. D. Reynolds *964
Rockford hydraulic planer-shaper with side head *969
Sharpeners — Rogers automatic circular saw sharpener *202
Wells bent tap *1011
Wells for die sinking cutters *822
Wells for metal pattern scrapers *859
Wells tool *744

Shears and Shearing:
Buffalo billet shear *855
"Buffalo" universal shears *968
"Handbib" nibbler and rod cutter *546
"Kleenkut" shear knives 392
"SN" plate slitting, trimming, and beveling shears. United Machine Tool *315
Shells, bulging and flanging. C. H. Willey. *623
Shop equipment review 77

Shops:
Changes in locomotive shop practice. M. H. Westbrook 448
Clean shops—Skill in a Japanese shop 940
Fabrication shop for large-scale welding *43
Further evolution of a job shop. Frank J. Oliver, Jr. *529
In a Chinese shop. J. R. Godfrey *987
Knowing where work is in the shop. Fred H. Colvin *325
Machine shop extraordinary to the "Queen of the Seas." E. J. Tangerman *799
Odds and ends in a railroad shop. H. P. Leonard *261
Progress in machine shop practice. K. H. Condit (Abstract of paper at A.S.M.E.) 14
Railway tools in a Canadian shop. F. W. Curtis *977
Shore hardness indicator with large table. *1050
"Simplex" engraving machine *859
Nesting bins *1007
"Utility" press *279
Slotting fixture. C. H. Willey *998
Société Genevoise micro-indicator stand. *706
Micro-indicator tube *239
Societies and associations. E. F. Du Brul. 597

Society of Automotive Engineers:
Annual meeting 244a
Celebrates its silver anniversary. H. Chase *861
S.A.E. celebrates (ed) 886

Soldering:
"Clarostat" electric-soldering-iron heat controller *1010
"Esico" industrial electric irons *281
Ladle for pouring solder. E. Andrews. *926
Underlying principles of soft soldering. —Discussion. A. Eyles 532
South Bend metric engine lathes *433
"New Model" lathe *672
9-in. precision lathe *240
Spacing device for a milling machine. M. Harris *627
Spark testing of metals (Ref. Book Sheet) 703
Specifications, standardized. Harry Kaufman 13
Speed changers, Crocker-Wheeler, types C. & S. *72

Page

Speed Reducers:
Boston *675
Cullman *673
Falk right-angle drive *277
"Heliocentric" and "Revocentric" *546
James spiral-bevel-gear right-angle *677
"Titan" helical and herringbone speed reducers *967
Sperry, Elmer Ambrose (ed) 1038
Spindle-feed, automatic for countersinking. Ernest Foldvary *274
Gridley four spindle automatic *781
Holding drills in a tailstock. C. Kugler 962
Spinning—Spheres for man-made lightning. H. W. Tenney *359
Spline weights. M. Schwam *926
Splitting bearing caps on connecting rods. *823
Spray gun—Tarring tanks with gun. J. Kelly 848

Springs:
Calculating spring capacities. J. H. Finkelstein 814
Coiling long springs. Harold C. Rose. *739
Rubber used for stripper springs. Chas. H. Willey *196
Spring tool for turning fillets. John Place. *231
Stamets automatic spline milling machine. *542
Standard Die & Tool Co.—Fixture for holding a cylinder block while end is milled *515
Jigs for drilling and reaming *515
"Standard" high-speed snagging grinder. *707
Standard prices. John R. Godfrey 346
"Standard" tungsten-carbide grinder *1007

Standardization:
Trends in buying stimulate standardization. I. J. Fairchild 873
"Stanley-Ajax" electric hammer *509
Stanley-Crowe safety saw *544
Stanley—Unishear metal cutting tools *711
Starrett cutter clearance gage *934

Starters:
Condit across-the-line starter *471
Condit air motor starter *638

Steel.
Ammonia-treated gage steel. A. J. Wormwood 452
Nitriding steel (Ref. Book Sheets) 741
Plating stainless steel. W. E. Warner. 884
Selection of sheet steel for deep drawing. W. H. Graves *718
Tempering cutting tools. J. T. Towlson 248
Testing steel sheet for weldability 790
"U. S. S." chromium steel 1047
Weights of round steel bars. L. F. Swenson 979
Steering gear manufacture. J. B. Nealey. *519
Stockholders increase — Two hundred thousand (ed) 386
Stock room—Keeping tabs on stocks in hand and on order. John R. Godfrey 483
Strand flexible-shaft machine *752
Strapping, "Colorgraph" box strapping 507
Striper—Paasche "Hudson" production *969
Stripper for multiple punch. W. J. Tangerman *884
Paired for odd-shaped work. W. Wells. *922
Studs—Removing broken studs. R. H. Kiddle *538
Stuebing "Blue streak" tin-plate lift truck *638
Sturdimatic roller bearing live center *708
Sundstrand rigidmil milling machine *236
Swaging machine — Langelier automatic taper pin *318
Langelier spoke swaging machine *430
Swift heavy-duty spot welders *822

Switches:
Allen-Bradley automatic pressure switch *673
Allen-Bradley single-phase starting switch *547
Cutler-Hammer overload for small motors *392
"E. C. & M." type NT master switch. *639
General Electric magnetic reversing. *747
Westinghouse linestarter and safety switch *636
Westinghouse safety switches *974

T

Tactograph, inspection and repair. Chester B. Lord *527
Tailstock—live centers. W. P. Childs *883
Tank and gun for spraying body noise deadening compound *36
Taper holes—device for measuring. Harry W. Clifford *384

Tapping:
Garvin heavy-duty automatic machine. *353
Globe automatic tapping machine *351
Gray "Super" universal attachment. *320
High-speed tapping fixture for small parts. C. W. Hinman *852
Kingsbury drilling and tapping machine *787
Landau drilling and tapping machine. *750
Preventing breakage of small taps.—Discussion. R. H. Kasper 25
Preventing the breakage of small taps. —Discussion. W. S. Rowell *847

Page

Simple tapping fixture. Chas. H. Willey *347
Taps, preventing breakage of small.—Discussion. Andrew J. Schwartz; J. T. Towlson 65, 68
And screw threads. Ref. Book Sheet). *29

Tariff:
Brake on industry (ed) 386
New rates on machinery 714a
Taylor-Winfield universal four-corner flash welder *201
Tempering cutting tools. J. T. Towlson. 248
Templates—"Maco" adjustable template. *860
Terkelsen electric molding machines *507
Terminals, assembling fixtures for. Chas. H. Willey *311
Testers—"Mikrotast" tap lead tester *204
"Mikrotast" wire tester *201
Testing machines, review of *121

Testing and Tests:
Cable and wire testing machine. Olsen *75
Device for, globe valves for tightness. Frank J. Oliver, Jr. *65
Mohr & Federstaff Brinell tester *1009
Oxweld portable testing machine *858
Thomas bending and straightening machine. *431
"Thor" rotary pneumatic grinders *74

Threading:
Aluminum for threaded parts. J. D. Porter 762
Brown & Sharpe automatic screw threading machines *970
Cutting a thread on a taper. J. T. Towlson 348
Landis bolt threader and former *933
Machines, review of *111
Oster pipe threading machine *817
Screw-thread helix angle, diameter, and lead determinations. (Ref. Book Sheet) 631
Oster three-way pipe threader *898
Small screws threading. O. A. Wagner 537
Thread cutting stund. H. T. Collinet. *851
Thread rolling on the screw machine. C. A. Coppack 232
Tool for cutting precision threads. T. W. Hobbs *627
Threads, screws, and taps. (Ref. Book Sheet) *29
"Timesaver" lapping compounds 1006
"Titan" helical and herringbone speed reducers *967
Safety drive chucks *1043
Toledo crank press *634
Folding steel horse *822

Tolerances:
German and Skoda tolerances compared.— Discussion. N. N. Sawin. 625
Machining a honeycomb to close tolerances. Chas. M. Reesey *362
Selective inspection cuts assembly costs. W. G. Holmes 806
Tolerances and tools. D. W. Ovaitt. 903

Toolholders:
Armstrong for tungsten-carbide bits. *1048
For high-speed toolbits. J. T. Towlson *778
Gooseneck, for shaper. H. L. Wheeler *66
"Wedge-lock" holder and boring bar. *1040
Toolroom—is the toolroom passing? Discussion. L. O. Brown 361

Tools:
"A-S-E" all-steel tool cabinets *895
"A-S-E" all steel tool chest *969
Baker-Case machinists' chests *897
Decorating flat surfaced. Raymond H. Dauterich *272
Dual and multiple tooling. P. H. Mayoh *19
Duplex wrench for valve adjustments. Max Schwarze 348
Emergency repair for a threaded arbor. C. C. Tommey *668
European vs. American practice with Tungsten-carbide tools. Dr. N. N. Sawin 335
For bending ears on clamps. C. H. Willey *962
For buffing rubber disks of emergency valves. John C. Grover *26
For cutting precision threads.—Discussion. M. Harris 1034
For drilling, reaming and sport facing. H. L. Wheeler *628
For handling unusual work. F. H. Mayoh *1033
Gashing circular forming-tools. Fred H. Schofield *193
Gerstner tool chest *897
Holder or guide for roll stock on a punch press. Henry C. Francis *422
Keeping a line on tools.—Discussion. J. T. Towlson 535
Knurling tool for use in a turret. Chas. H. Willey *229
Making a temporary stepped mandrell. E. R. Vogel *812
More chips from tungsten-carbide tools. F. W. Curtis *608
Necking tool. Geo. W. Hammitt *274
Planes, shaper, or miller jack. (Ref. Book Sheet) *779
Press tools for cutting off, piercing and forming. C. H. Willey *607
Press tools for trimming screw heads. Chas. H. Willey *421
Radius tool. L. P. Simoneau *630

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Ready-made sketches for the toolroom. C. W. Hinman *195
Review of small *136-136
Safety tool for the press operator. A. R. Kling *310
Speeding tool design with typical outlines. Col. J. O. Johnson *980
Stopping waste in tool service. H. L. Bradford 401
Temporary tool for notching and bending. Chas. H. Willey *421
Tolerances and tools. D. W. Oviatt. 903, 956
Tool economy. Chas. H. Willey *421
Toolroom convenience. (Ref. Book Sheet) *197
Tungsten-carbide effect on machine-tools 227

Tractors:

All-modern equipment produces Allis-Chalmers tractors. William Watson. *436
Case-hardening practice for tractor gears. J. Fletcher Harper *449
Completely mechanized foundry for tractor castings. E. A. Harrison ... *445
Heavy castings and special machines. H. W. Liebert *453
Parts, heat treatment and inspection of caterpillar *22
Special-purpose equipment for accurate tractor parts. Frank J. Oliver, Jr.. *458
Treads for track-type tractors *988
Threads for track-type tractors *1016
"W & K" industrial tractor *205
Why a gas-engine-driven tractor? C. M. Hermens 1023
Trade associations—No time for short cuts (ed) 30
Trade-ins, scrapping the (ed) 632
Trade journals-molding industrial opinion. F. M. Feiker *587
Trade Schools—Co-operation in vocational education. R. F. Carey 697
Transmission equipment, review of *129
Transue & Williams conveyor chain *1043
Trent Electric Babbitt pot *888
Electric furnaces for small parts *858
Trigonometric functions, aid in remembering. E. Simonsen 67
Trimmers—Manville capscrew trimmer *671
Trimming plates *733
Trolley—Louden motor-driven *895

Trucks:

Leckie elevating die truck *472
"Red Junior" Barrett lift truck *389
Stuebing "Blue Streak" tin-plate lift.. *628

Tungsten Carbide:

Field facts on tungsten carbide (ed).. 854
Grinding tungsten-carbide tools. (Ref. Book Sheet) *669
Machining with tungsten-carbide 422
More chips from tungsten-carbide tools. F. W. Curtis *608
More chips from tungsten-carbide tools. Discussion. C. B. Lord 985
Properties and applications. (Ref. Book Sheet) 349
Prosser grinding gage for tungsten-carbide tools *707
Used for cutting armored tube. Henry A. Ingram *39
Worth its weight in tungsten-carbide (ed) 468
Tools—European vs. American practice. Dr. N. N. Sawin 335

Turning:

Attachment for, spherical surfaces. Franz Bermann *26
Welling crankshaft, and cheeking machine *35

Page

Turning machine—Economy double-end machine *973
Foster special crank turning machine.. *242
Typesetting—tooling for typesetters. R. R. Mead *825

U

"United" dial caliper *351
United Machine Tool—"SN" shears *315
"U. S." blower and vacuum cleaner *711
"U. S." electric drills with improved chuck spindles *503
U. S. Government aids to industry. Julius Klein 590
"U. S. S." chromium steel 1047
"U. S." standardized die sets *1008
"Universal" nitralloy bushings 821
"Tri-way" horizontal boring machine. *354

V

Vacuum cleaner and blower—"U. S." *711
Breur industrial *710
V-block and clamps for right-angle layouts. Theodore Kruger *68
Valve liners, jacking in. Frank J. Oliver, Jr. *27
Van Dorn portable electric saw *677
Vapor degreaser for impervious materials. Carrier Co. *74
Verson straight-side steel-frame press *391
Vise, ball thrust-bearing applied to vise screw. D. W. Allis *702
"Palmgren" adjustable machine *1048
Air-operated vise. G. A. Luers *922
Cincinnati plain and swivel vises *387

W

"W & K" industrial tractor *205
Wachs metallic electrode holder *712

Wages:

Plus incentive to high production. F. T. Daniel 661
Review of certain wage systems. James R. Cornelius 342
Wallace hand jointer *672
Wappat "Red Streak" bench-type grinder.. *75
War Department—a peacetime call (ed) .. 234
Warner & Swasey Co.—The future. P. E. Bliss 867
Washers, making, in small lots. Charles Kugler 67

Waste:

How much junk is under your benches? Henry C. Francis *665
Southern Pacific R.R. Shops utilize.. *189
"Wedge-lock" toolholder and boring bar.. *1040

Welders:

Lincoln automatic welder for cross brake shafts *639
Lincoln automatic wire wheel welder.. *205
Swift heavy-duty spot welders *822
Westinghouse "flex-arc" welders *508
Wilson 100-ampere welder *502

Welding:

Arc-welded welding fixtures *188
Bronze welding copper *528
Drive wheels. Frank J. Oliver, Jr... *11
Equipment, review of *130

Page

Fabrication shop for large scale *43
Fusion welding of aluminum. (Ref. Book Sheet) 885, 927
General Electric—welding a seam inside a circuit breaker tank *788c
Joining by separation (N) *860c
Machines, review of *113
Oxyacetylene, in nickel 21
Oxyacetylene welding in Korea. F. H. Colvin *908
Role of atomic hydrogen in welding. S. Martin, Jr. 301
Selecting the type of, for the job. T. H. Booth *47
Testing steel sheet for weldability ... 790
Welded automobile bodies and the oxy-acetylene torch. Joseph W. Meadowcroft 521
Welded-on overlays in machine design. Miles C. Smith *265
Welding and cutting. (Ref. Book Sheet) 275

Welding Equipment:

Automatic Electro feeding device. General Electric Co. *200
Flexible fixture for welding. Harry Shaw *536
Lincoln "lightweld" welding rod 892
Lincoln "Stainweld A" welding rod... 746
Oxweld steel welding rod 431
Oxweld welding blowpipe *471
Rego "Economizer" automatic shut-off for welding gases *205
"Rego" welding torch *202
Rod for hard facing, "Borod" 31
"Weldite C" fluxed welding rod 470
"Weldite C" fluxed welding rod 72
Fillet putty *1042
Multi-stage regulator *432
Wells—Bent tap sharpener *1011
Cutter sharpener *1010
Drill grinder *541
Round cutter grinder *548
Sharpener for die sinking cutters *822
Sharpener for metal pattern scrapers. *859
Thread milling machine *710
Tool sharpener *744
Westcott drill chuck *1045
Western "low-hung-drive" radial drills *506

Westinghouse:

Carriage driving unit *968
Double-reduction gear unit for steel mill drive *676
"Flex-arc" welders *508
Forms supply company 206c
From nine-inch slab to welded motor frame *682
Large sphere spark gap to measure voltages. H. W. Tenney *359
Linestarter and safety switch *626
"Phos-copper" welding alloys 860
Safety switch *974
Wheels—Carter detachable rim wheel for bandsaws *890
Renewing wheel flanges of trolley cars. *305
Wilson 100 ampere welder *502
Woodworking equipment, review of *132
Work, defective (ed) 234
Wrapping rolls, Buffalo *352
Wrenches—Quadruple open-end wrench. L. Coon 1034
"Wright" dynamic, lowering circuit controller for crane hoists *282

Z

Zeh & Hahnemann percussion power press. *747
Pillar toggle presses *889
Zinc—Uncommon properties of a common metal. Robert M. Curts *413

AUTHORS' INDEX

Page

ADDISON, TOM. Providing lifting devices on machine tools *902
Alexander, Robert S. Buying or making special tools 18
Compulsory membership in the mutual aid 770
Is the customer always right? 1020
Sales or sincerity? 944
Should special work be segregated? .. 908
Allenby, W. F. Paying for dependability .. 411
Allis, Dexter W. Ball thrust-bearing applied to a vise screw *702
Alt, Carl G. Device for grinding work that is not straight *384
Andrews, E. Ladle for pouring solder .. *926
Armour, Will. Sales or sincerity? 759
Should salesmen design? 984
Avery, C. W. New Murray unit finishes and trims 900 bodies a day *476
Stamping and assembling 100 bodies an hour *397

BAILEY, DAVID C. Safety device for presses 999
Baker, D. A. Beeswax for self-equalizing fixtures *666
Die that was a failure *1036
Ball, Henry. Adapter for universal indicator 962
Barth, Albert H. Upsetting production schedules 870
Barth, Charles F. Should price or payroll be cut? 798

Page

Belbes, George. Learning from the small shop 525
Should salesmen design? 943
Upsetting production schedules 252
Bell, Joseph. Is the customer always right? 983
Benjamin, J. Malvern. Is budgetary control a cure-all? 798
Mottoes in the shop 952
Should special work be segregated? .. 908
Who should do the estimating? 403
Benton, J. M. What you do, or what you get done? 185
Bermann, Franz. Attachment for turning spherical surfaces *26
Compulsory membership in the mutual aid 803
Concavities and convexities *419
Does a highly developed system pay? . 176
Fitting the older worker for his job .. 517
Friendliness in business 214
Making a manager out of a foreman .. 652
Paying for dependability 411
Raising the working efficiency 621
Ratio of raw materials to production 721
Sales or sincerity? 834
Should a plant take an annual inventory 870
Betz, Wm. C. Accurate drilling of small holes *813
Chain store problem 991
Bidwell, Marshall. Precision boring in a vertical milling machine *921
Bliss, Philip E. The future 867

Page

Bode, J. C. Buying or making special tools 18
What price titles? 869
Booth, T. H. Selecting the type of welding for the job *47
Braasch, Herbert. Law as applied to industry 345
Bradford, H. L. Stopping waste in tool service 401
Bramwell, Arthur. New drills and old men 951
Too much co-operation 841
Brookman, H. E. Milling vise with hold down jaws *28
Brown, Harrison G. Ethics of making a change 731
Brown, Andrew W. Concavities and convexities 379
Brown, L. O. Advising employees about their affairs 337
Compulsory membership in the mutual aid 53
Equipment replacement in slack periods 613
Foremen and the wage bonus 1028
Games at the noon hour 186
How long should records be preserved? 614
Is the toolroom passing?—Discussion 361
Making a manager out of a foreman. 252
More ways than one 299
More ways than one 338
Mottoes in the shop 760
Paying for dependability 411
Quick-acting clamping device *228
Sales or sincerity? 983

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Should a plant take an annual inventory? 403
Should salesmen design? 1020
Should special work be segregated? 943
Smoking during working hours 373
Tempering general purpose tools 259
What price titles? 869
Who should control routing? 908
Will it pay to enlarge the plant? 482
Bryce, William. Closing the doors to late comers 1027
Eating during working hours 769
New drills and old men 696
Scheduling locomotive repairs in a Japanese shop.—Discussion 905
Should special work be segregataed? 834
To whom should the chief inspector report? 944
Burnham, H. J. Compulsory membership in the mutual aid 411
Friendliness in business 46
Keeping machines on the job 696
Mottoes in the shop 842
Puller for gears and couplings *997
Upsetting production schedules 290
Who should do the estimating? 651
Buyers, D. E. Is incentive necessary? 1019

CAIN, W. F. Another "Bent hole" *498

Carey, R. F. Co-operation in vocational education 697
Cawley, F. J. Preventing blanks from slipping in drawing *230
Chamara, Martin B. New drills and old men 843
Chapman, W. A. J. Constant chord gaging *753
Chase, Herbert. Bonderizing and enameling as practiced by Chrysler *755
Comment on American passenger-car gearsets *909
Die-pressed parts reduce production costs *835
Ford body assembly at Chester plant. *1021
Hot-pressed brass parts production *879
S.A.E. celebrates its silver anniversary *861
Childs, Leslie. Making safety rules, and enforcing them 257
Childs, W. P. Live tailstock centers *883
Clark, Wallace. American management methods in a European car shop *511
Clarke, E. J. Press guards—good and bad 700
Clause, E. P. Who should control routing? 688
Clawson, C. D. Do's and don'ts in vitreous enameling *947
Pickling for vitreous enamel *295
Clifford, Harry W. Device for measuring taper holes *384
Cochrane, L. J. American industrial machinery exports for 1929 282a
Collinet, H. T. Thread cutting stunt *851
Colvin, Fred H. Assembling American cars in Japan *522
Building machine tools and locomotives in Osaka *648
China as a machine market *945
Handling air-brake parts in a Japanese shop *813
High spots in the Pierce-Arrow cylinder line *4
How small Japanese shops build bicycle parts 846
Japan also builds electrical machinery *764
Japan as a market for American machinery 268
Japan has set a precedent for the next World Engineering Congress 378
Jigs in Japan *495
Knowing where work is in the shop *325
"Old man" for boiler front ends *849
Oxyacetylene welding in Korea *998
Repairing locomotives in a university shop in Mukden *791
Scheduling locomotive repairs in a Japanese shop *207
Condit, Kenneth H. Fulfilling replacement promises; from an interview with Paul C. DeWolf 789
Progress in machine shop practice. (Abstract of paper at A.S.M.E.) 14
Will nineteen thirty be as good as nineteen twenty-nine? 1
Cook, Alfred. To whom should the chief inspector report? 517
Coombes, Leonard. Old kinks and new ideas 992
Smoking during working hours 877
Coombs, Gilbert G. Advising employees about their affairs 622
Eating during working hours 337
Ethics of making a change 185
Smoking during working hours 941
Coon, L. Quadruple open-end wrench *1034
Coppack, C. A. Slitting die discussion 193
Thread rolling on the screw machine.—Discussion 232
Cornelius, James R. Combined bending and curling tool *273
Keeping machines on the job 696
Review of certain wage systems 342
Who should be laid off first? 622
Will it pay to enlarge the plant? 331
Cornwall, Clifford. Support for gears in a hobbing machine *1035
Cox, Joseph J. Equipment replacement in slack periods 330
Crawford, C. A. Longer-lived equipment for metal pickling *58
Crawford, Herbert F. Special boring head for milling machine *999
Curley, John J. Who should do the estimating? 329

Page

Curtis, Frank W. Concavities, convexities and ovals *463
Dies and tools for four-piece rear-axle housings *219
More chips from tungsten-carbide tools *608
Out of the scrap heap *189
Railway tools in a Canadian shop *977
Tooling for 250 pistons an hour *489
Ways and means of riveting the sub-assemblies for calculating machines *343
Curts, Robert M. Uncommon properties of a common metal *413

DANIEL, F. TREVOR. Plus incentive to high production 661
Darby, V. C. Should the workman share responsibility 53
Darling, H. M. Learning from the small shop 622
Paying for dependability 259
Tempering general purpose tools 53
What you do or what you get done? 185
Dauterich, Raymond H. Bonus for the ambitious 17
Paying for dependability 186
Should price or payroll be cut? 983
Tools for decorating flat surfaces *272
Who should do the firing? 722
Decker, J. Mottoes in the shop 991
Too much co-operation 1027
Who should do the firing? 944
Deeley, H. S. Should salesmen design? 984
Delbridge, Ernest. Simple cam grinding fixture *961
Delenk, W. N. Simple flush-pin gages *1034
De Pasqual, Peter. Should estimates be given operatives? 651
Dillon, L. J. To whom should the chief inspector report? 652
Dion, Emile H. Ethics of making a change 373
Doris, L. R. Games at the noon hour 224
Doughty, F. S. Clamp for micrometer extension rods *630
Simplifying laying out *667
Du Brul, Ernest F. Societies and associations 597
Support for machine tool research.—Discussion 757
What is normal operation in the machine tool industry 960
Dunham, Geo. W. Simple checking system to reduce excess cost *844
Dunstone, D. R. Problem in shaper work.—Discussion *312
Dunton, O. M. To whom should the chief inspector report? 687

EDWARDS, JOHN. Support for machine tool research 462
Support for machine tool research.—Discussion 837
Ellis, J. Improving index plates *1036
Elvin, W. J. Who shall be laid off first? 374
Erickson, A. F. To whom should the chief inspector report? 613
Eyles, A. Underlying principles of soft soldering.—Discussion 532

FAIRALL, EARL. Old kinks and new ideas 804
Fairchild, I. J. Trends in buying stimulate standardization *873
Falk, Otto H. An act of faith in modern equipment. Allis-Chalmers Model U tractor 435
Fann, A. T. Is budgetary control a cure-all? 1019
Off with the old, on with the new 901
Smoking during working hours 769
Felker, F. M. Molding industrial opinion *587
Feltner, George H. Drill jig built up by welding *28
Set-ups for machining crossheads *465
Ferris, Jack. Holder for knurling and cut-off tools *25
Fetter, Arthur. Smoking during working hours 841
Feucht, Albert. Adjustable angle plate *852
Wedge-operated V-block *776
Fiedler, H. F. Improvised grinding fixture. *778
Keeping machines on the job 992
Learning from the small shop 621
More ways than one 411
Should the workman share responsibility? 17
What you do or what you get done? 339
Fielding, George. Learning from the small shop 187
Should the workman share responsibility? 299
What you do or what you get done? 338
Finkelstein, Jacob H. Calculating spring capacities 814
Firnhaber, Fred A. Improved spline milling cutters *177
Fischer, W. E. Equipment replacement in slack periods 45
Fish, Thomas. Gooseneck toolholder for the shaper—discussion *630
Fitzgerald, James F. Spring song 916
Fletcher, C. Norman. Who shall be laid off first? 621
Foldvary, Ernest. Automatic spindle-feed for countersinking *274
Cross-keys for holding heavy punches. *194
Gages for checking tapers *383
Production turning on an engine lathe. *196
Safety clamp for cutter wedges *312
Fontanella, A. Extending the travel of a screw *849
Forbes, A. W. Just what is an apprentice? —Discussion 774

Page

Forman, S. Smoking during working hours 805
Forsman, Carl G. Dial plate with adjustable nests *1033
Positive knock-out for progressive dies. *999
Fortune, Seth. Press tools for ammeter covers—discussion 999
Francis, H. C. Double fixtures for milling plier parts *24
Holder on guide for roll stock on a punch press *422
How much junk is under your benches? *665
Frank, C. W. Air-operated clamp for holding hub liners *814
Convenient rack made from discarded parts *668
Frank, Thomas B. Executive interest in costs 50
Should price or payroll be cut? 688
Franklin, Chester H. Checking outlines on contour gages *422
Making tumbling barrels do double duty *194
Franklin, O. J. Storage rack for layout boards *26
French, Clifford H. Concavities, convexities and ovals *464
Peening retaining rings with air hammers *740
Freund, C. V. Just what is an apprentice? *181
Freyermuth, J. R. Who should do the firing? 797
Why conferences anyway? 951
Furey, C. F. Bonus for the ambitious 53

GAGNON, E. E. Should price or payroll be cut? 869
Should salesmen design? 721
Should special work be segregated? 759
Gamble, Ralph M. Making and using a sine-bar 811
Gammons, G. W. Precision plating through timed equipment *492
Gibson, Geo. W. Who should do the firing? 833
Gilcreas, Walter F. Chain store problem. 915
Foremen and the wage bonus 952
Should overhead be uniform? 984
Should price or payroll be cut? 943
Who should control routing? 723
Godfrey, John R. In a Chinese shop *987
Keeping tabs on stocks in hand and on order 483
Seen and heard 227
Goldschmidt, Dr. Hans. Large height gage. *923
Gordon-Sale, C. B. Nickel plate on aluminum 409
Graves, W. H. Selection of sheet steel for deep drawing *718
Grigg, A. M. Games at the noon hour 259
Grover, A. E. Costing for profit 899
Grover, John C. Tool for buffing rubber disks of emergency valves *26
Gunn, Geo. H. Accuracy and speed in detailing 466
Gutsch, F. J. Overcoming the smoking habit in oil-fired furnaces *417
Gwiazdowski, A. P. Bench lathe of unusual design *654
Lip clearance gage *838
Student jig design *923

HAGEMANN, GEORGE E. Ford stock and traffic control *975
Hahn, J. H. Mold for relining laird-type crossheads *848
Planing locomotive crossheads *67
Reclaiming locomotive crossheads *628
Tool for facing large nuts *777
Hamilton, W. E. Advising employees about their affairs 259
Equipment replacement in slack periods 289
Who shall be laid off first? 525
Will it pay to enlarge the plant? 45
Hammitt, Don R. Maintenance of motor bearings 775
Supporting the outer ends of broaches *702
Hammitt, Geo. W. Adjustable necking tool *274
Quick-change boring heads *922
Hargrave, T. H. Bonus for the ambitious. 339
Night shift 175
Should a plant take an annual inventory? 722
Will it pay to enlarge the plant? 614
Harper, J. Fletcher. Case-hardening practice for tractor gears *449
Harris, Matthew. Spacing device for a milling machine *627
Tool for cutting precision threads.—Discussion 1034
Harrison, E. A. Completely mechanized foundry for tractor castings *445
Haselgrove, R. L. Games at the noon hour 17
Should special work be segregated? 1020
Hays, C. A. Who shall be laid off first? 659
Hazzard, H. I. Ethics of making a change 916
Paying for dependability 373
Heath, Clarke B. Formula for measuring dovetails *272
Henry, C. L. Should special work be segregated? 944
Who should do the estimating? 797
Herbert, Edward G. Hardness by "Cloudburst" *917
Hermens, C. M. Why a gas-engine-driven tractor? 1023
Herr, Homer A. Boss, or advisor? 843
No verbal orders accepted 877
Should price or payroll be cut? 833
Hewitt, R. G. Concavities and convexities. *381

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Games at the noon hour 223
Equipment replacement in slack periods 517
Hill, S. C. New drills and old men 992
Hinman, C. W. Double-acting tools for a press *961
Feeler blocks on milling fixtures *1036
High-speed tapping fixture for small parts *852
Quick-acting locking lever *231
Ready-made sketches for the toolroom. *195
Three-dimension fixture for cutting cams *270
Hinton, J. C. What price titles? 722
Hobbs, T. W. Does a highly developed system pay? 46
Should estimates be given operatives? 721
Tool for cutting precision threads *627
Holmes, Walter G. Selective inspection cuts assembly costs 806
Homewood, J. Closing the door to late comers 695
Keeping machines on the job 915
Hopgood, W. J. Why conferences anyway? 916
Houston, E. No verbal orders accepted .. 1027
Hucke, R. H. Thirty-five minutes per carload *993
Hudson, Frank C. Air hose protector *466
Huyett, R. B. What price titles? 833
Hyde, Frank A. Bonus for the ambitious. 339
Hyler, John E. Flexible shaft possibilities. 839

INGLERIGHT, F. L. Advising employees about their affairs 721
Learning from the small shop 412
Paying for dependability 338
Should estimates be given operatives? 687
Smoking during working hours 841
Too much co-operation 951
What price titles? 797
What you do or what you get done?. 300
Ingram, Henry A. Armor plate ordeal for tungsten-carbide *39
Irmer, Charles B. Cutting a double thread wormwheel with a single thread hole 232

JACOBSON, GEO. E. High-speed graduating fixture *850
James, H. Does a highly developed system pay? 289
Equipment replacement in slack periods 687
Lamps for inspecting small holes .. *926
Neglecting letters loses an order 176
Should the workmen share responsibility 186
What should we teach apprentices? .. 9
What you do, or what you get done?. 412
Who should control routing? 983
Will it pay to enlarge the plant? 251
Jenne, Geo. B. Bonus for the ambitious .. 223
Closing the door to late comers 992
Johnson, Carl. Mottoes in the shop 1028
Johnson, Col. John O. Speeding tool design with typical outlines 980

KAMPMEIR, FREDERICK. Is budgetary control a cure-all? 432
Kasper, R. H. Milling machine set-up ... *630
Mottoes in the shop 695
Preventing breakage of small taps.—Discussion 25
What price titles? 869
Kaufman, Harry. Does a highly developed system pay? 251
Equipment replacement in slack periods 214
Is budgetary control a cure-all? 517
Standardized specifications 13
Tempering general-purpose tools 186
Keeler, E. E. Device for testing the grinding of hobs *629
Keeney, Robert M. Economics and economies of heat-treating *225
Kehres, Geo. W. Cutting helical grooves in a cast-iron roll *851
Keil, Rudolph. Accurate scribe block for toolmakers.—Discussion 66
Kelly, Frederick W. Smoking during working hours 805
Kelly, Joe. Preventing soap streaks in paint 628
Tarring tanks with a spray gun 848
Kentish-Rankin, I. L. Tempering general-purpose tools 186
Kiddle, Richard H. Removing broken studs *538
Kilburn, Edwin. Intermittent friction motion *925
Kilroe, H. B. Insight into outboards 689
Kimball, Dexter S. Role of engineering education *575
Kirk, H. N. Jig for drilling holes in mica *465
Kirkbride, Charles E. Should salesmen design? 798
Kirkpatrick, W. A. How long should records be preserved? 365
Smoking during working hours 877
Klein, Julius. Government aids to industry 590
Kling, A. R. Magazine feed for a punch press *24
Safety tool for the press operator .. *310
Klingman, A. R. Problem in shaper work.—Discussion *229
Klingstein, Fred. What price titles? 613
Klyne, Charles. Sales or sincerity? 614
Who should do the estimating? 289
Knight, W. H. How long should records be preserved? 760
Koch, Leonard J. Ethics of making a change 842

Page

Koch, Reinhold. Flanging splash pans on a lathe *231
Kopp, Joseph. Simplified binding device .. *852
Kraut, S. B. Punching shells for light sockets *497
Kruger, Theodore. Clamping fixtures to fit T-slots *272
Jig for center drilling *739
Safety sign for ladders 831
V-blocks and clamp for right-angle layouts *68
Kugler, C. Accurate drilling of small holes *232
Centralizing gear cutters *702
Correcting errors in jig work *498
Fixture for checking keyways *422
Holding drills in the tailstock spindle 962
Making washers in small lots 67
Spring flexible coupling.—Discussion. *739
Kyn, Joran. Should price or payroll be cut? 908

LAMB, HAROLD. Equipment replacement in slack periods 722
Making a manager out of a foreman 175
Who shall be laid off first? 374
Lambert, B. E. Who shall be laid off first? 659
Lambert, William P. Who should do the firing? 1020
Lamont, Neil C. Sales or sincerity? 907
Landis, Wm. C. Learning from the small shop 659
Upsetting production schedules 176
Lattner, C. H. Off with the old, on with the new 991
Smoking during working hours 770
When personal tools are damaged 804
Leonard, H. P. Chuck for turning valve rings *229
Keeping machines on the job 373
Locomotive springs in process 340
Odds and ends in a railroad shop *261
To whom should the chief inspector report? 907
Tooling for high production over a long period *367
Lestyle, W. Eating during working hours 805
Paying for dependability 525
Using blind ads.—Discussion 514
What you do or what you get done? .. 300
Liebert, H. W. Heavy castings and special machines *453
Lincoln, W. B. Should estimate be given operatives? 870
Who should do the estimating? 365
Who should control routing? 760
Lincoln, W. B., Jr. Straightening the employment curve 763
Truing felt rolls in the lathe *997
Locke, L. L. Combination die for making lead gaskets *812
Ironing out tapered tubes *777
Roller-type bending die *738
Long, R. E. Should overhead be uniform? 983
Lord, Chester B. Babbitting as a positive operation *937
Inspection and repair of tactographs. *527
Management by exception 308
More chips from tungsten-carbide tools. —Discussion 985
Semi-portable conveyors in tractor production *215
Setting of threaded studs by means of the Temple Gun *245
What coolant shall we use? 407
What of the foundry? *679
Luers, G. A. Air-operated vise *922
Improvement in draftsmen's triangles. *998
Lundeen, C. V. Rotary forming *912
Lyon, Lieut. A. J. Aluminum alloys for pistons and cylinder heads 996

MCARD, G. W. Reproducing drawings to a different scale 271
McCormack, Bernard. Making a manager out of a foreman 213
Off with the old, on with the new .. 695
McCoy, R. E. Adjustable multi-spindle drill head *65
Pneumatically actuated drill jigs 55
McGraw, James H. Foreword 549
McKay, Norman. Automatic feed rolls for a punch press *347
Macomber, Glen. Smoking during working hours 841
Malliet, W. H. Records of minor employees 949
Manger, Charles. Keeping machines on the job 951
Manning, E. Shortening labor in design calculations.—Discussion 491
Mansfield, F. M. Europe also exports .. 664
Mansfield, Henry. Extensions for chuck jaws *348
March, S. R. Our changing exports 736
Mardy, W. Does highly developed system pay? 652
Markey, L. E. Upsetting production schedules 330
Martin, S., Jr. Role of atomic hydrogen in welding 301
Masek, John A. Apprenticeship courses for seniors 484
Matter, James K. Chain store problem 1027
No verbal orders accepted 842
Pensions or leaky payrolls? 834
Should overhead be uniform? 869
Should special work be segregated? .. 721
Why an organization chart? 1020
Matthews, Burton. Eating during working hours 770

Page

Maus, T. J. Who shall be laid off first? .. 411
May, John Mark. How long should records be preserved? 290
No verbal orders accepted 952
Too much co-operation 915
What price titles? 907
Who shall be laid off first? 337
Mayoh, F. H. Dual and multiple tooling .. *19
Tools for handling unusual work *1033
Mead, R. R. Tooling for typesetters *825
Meadowcroft, Joseph W. Welded automobile bodies and the oxy-acetylene torch 521
Miller, Geo. R. What price titles? 797
Miller, Glen J. Reaming taper holes to a given depth *740
Millington, D. New drills and old men .. 803
Miltoun, Francis. Europe's electro-technical industries survey their export markets 396c
Moore, H. Constant-center Vee blocks *811
Driving work by three dogs *1000
Finding centers of new teeth in a repaired gear *812
Morrison, C. J. Making a manager out of a foreman 366
Should price or payroll be cut? 760
Morrison, R. J. What you do, or what you get done 224
Mumper, Arthur. Cam-operated milling fixture *701
Practical heat-treating in the small shop *699

NADON, C. L. Eating during working hours 299
Needham, W. Roland. Accuracy and speed in detailing—discussion 1035
Colored inks for drawing clarity—discussion 775
Dimensions of recessed pockets for nuts—discussion 274
Finding clearance for work on boring mills—discussion 701
Fitting the older worker for his job .. 403
Games at the noon hour 54
How much efficiency? Discussion 1025
Keeping a line on tools—discussion ... 955
Keeping machines on the job 1028
Practical contact for the designer—discussion 457
Raising the working efficiency 660
Recording changes on drawings 344
Should estimates be given operatives? 798
Upsetting production schedules 251
What you do or what you get done? .. 260
Nealey, J. B. Steering 6,400 steering gears through manufacture *519
Nielsen, Sigurd C. Smoking during working hours 622
Noffsinger, J. S. Bonus for the ambitious 621

OBERST, W. F. New drills and old men. 660
O'Brien, Arthur V. Improvised drill jig .. *738
Making endless belts *813
Oldacre, Wm. H. What coolant shall we use? 771
Oliver, Frank J., Jr. Device tests globe valves for tightness *65
Exact outlines of the blanks for Nash fuel tank covers are determined by careful experiment *172
Further evolution of a job shop *529
Grinding fixture for an odd-shaped casting *228
Heat-treating job shop organized along modern lines *375
Jacking-in valve liners *27
Nash "8" connecting rods in production *291
Nash "8" connecting rods in production *332
Special-purpose equipment for accurate tractor parts *458
Weatherproofing winterfronts *830
Wedge dies solve Nash press job *253
Welding drive wheels *11
Oviatt, D. W. Tolerances and tools 903
Owens, W. J. Eating during working hours 526
Equipment replacement in slack periods 651
Games at the noon hour 54
Making a manager out of a foreman .. 330
Night shift 251
Pensions or leaky payrolls? 1019
Sales or sincerity? 798
Should a plant take an annual inventory? 252
Should the workman share responsibility? 223
Spring song 878
What price titles? 518
Who shall be laid off first? 696

PALMER, J. O. B. How one shop reconditions locomotive superheaters. *405
Parham, O. C. Expansion arbor *538
Parkhurst, Douglas L. Pensions or leaky payrolls? 943
Sales or sincerity? 613
Pearson, P. H. Using blind ads—discussion 611
Who should be laid off first? 732
Pepperdine, J. W. Who should be laid off first? 660
Peshek, C. J. Keeping machines on the job 843
Peterson, Chas. A. Boss, or advisor? 915
Pfuchler, Fred. Concavities and convexities *381
Phillips, Marin. Safety helps to build financial independence 882
Phillips, S. B. Cyclic heat-treating of motorcycle parts *1032

(*) Illustrated (‡) Diagram (ed) Editorial

Page

Piranian, Edward V. Who should be laid off first? 185
Place, John. Spring tool for turning fillets. *231
Poore, C. A. Compulsory membership in the mutual aid 659
Porter, J. D. Aluminum for threaded parts 762
Potter, J. A. Accuracy in angle gazing.. *1024
Planning and design of stand type jigs *62
Prusznski, A. J. Problem in shaper work —discussion *924

RASTALL, W. H. Place of exporting in planned prosperity 169
Raymond, A. Safety tool for the press operator—discussion 925
Rebmann, Fred. One certain surface gage. *653
Reesey, Chas. M. Machining a honeycomb to close tolerances *362
Reothlisberger, John J. Fixture for bending copper and brass tubing..... *883
Reynolds, Samuel D. Problem in shaper work—discussion *964
Rich, I. B. Holding starter gears for tooth rounding *850
Richards, C. H. Eating during working hours 805
Why conferences, anyway?..... 731
Richards, Geo. M. Two drawers in benches —discussion 657
Robbins, Herbert C. Should overhead be uniform? 833
Roger, F. E. Flaming sawblade..... 191
Rose, Harold C. Coiling long springs..... *739
Ross, Cleland C. To whom should the chief inspector report? 481
Rowell, Wm. S. Hacksaw blades and some of their uses..... *536
Preventing the breakage of small taps —discussion *847
Rowland, N. Who should do the estimating? 687

SARGENT, JACK. Closing the door to late comers 951
Ethics of making a change..... 337
Too much co-operation..... 804
Sawin, Dr. N. N. European vs. American practice with Tungsten-Carbide tools 335
Gaging three-fluted taps..... *963
German and Skoda tolerances compared—discussion 625
Saxton, M. F. Sales or sincerity?..... 517
Why conferences anyway?..... 770
Schaphorst, W. F. Aiding the manufacturer to make repairs..... 757
How much efficiency?..... 61
Schinman, C. E. Who should do the estimating? 723
Schirmer, William. Games at the noon hour 54
Night shift 46
Schirmer, Wm. Should the workman share responsibility? 339
Schmidt, Frederick A. J. Buying or making special tools 18
Does a highly developed system pay?. 175
Hiring back old men first..... 9
New drills and old men..... 731
Should estimates be given to operatives? 366
Should special work be segregated?.. 518
Schofield, Fred H. Gashing circular forming-tools *193
Schroeder, Art. Should the workmen share responsibility? 185
Schwam, Morton. Colored inks for drawing clarity 193
Improvement in spline weights..... *926
Sales or sincerity?..... 870
Schwartz, H. A. Factors affecting machinability of malleable cast iron.. 871
Schwarz, Andrew J. Preventing breakage of small taps. Discussion..... 65
Schwarze, Max. Concavities and convexities *380
Concavities and convexities..... *420
Device for milling locomotive quadrants *310
Duplex wrench for valve adjustments. *348
Milling ports in a valve bushing..... *273
Searles, Ed. Ethics of making a change.. 804
Should estimates be given operatives? 614
Smoking during working hours..... 803
Shackleton, E. Scrapers for hard steel—discussion 649
Shafran, Philip F. Bonus for the ambitious 187
Shaw, Harry. Flexible fixture for welding. *536
Sherman, C. P. Ethics of making a change 842
Shields, E. R. Bonus for the ambitious.. 187
Foremen and the wage bonus..... 842
Raising the working efficiency..... 223
Who should control routing?..... 1019
Simonds, Alvan T. Climbing cycles of industrial production 10
Simoneau, Louis P. Radius tool..... *630
Simonsen, E. Aid in remembering trigonometric functions 67
Tempering of general purpose tools.. 223
Smith, Eli. Ethics of making a change... 732
Government work 952
Smoking during working hours..... 877
To whom should the chief inspector report? 651
Smith, John. Old kinks and new ideas... 877
Smith, Miles C. Welded-on overlays in machine design *265
Smith, P. Ford. Business ethics.—Discussion 306
Snyder, C. J. Phosphor-copper for welding and brazing *793
Sorenson, Niels J. Keeping machines on the job 842

Page

Steele, H. S. Protection for draftsmen's scales 851
Stemwedel, Adolf. Should estimates be given operatives? 943
Stern, B. J. Air-operated chuck..... *537
Automatic delivery mechanism for a press *66
Concavities and convexities..... *382
Indicating gage for roll retainers..... *383
Machine for rolling circles from strips 271
Safety device for handling press work *27
Stern, Marc. Die-casting today..... 1029
Sterritt, Elton. Depth gage for measuring liquids *25
Stevenson, James A. Should estimates be given operatives? 289
Should price or payroll be cut?..... 907
What should we teach apprentices... 45
Stiles, H. Smoking during working hours. 660
Stites, W. D. Foremen and the wage bonus 1027
Struker, Ralph N. Should the workman share responsibility? 488
Stryker, Ralph. Learning from the small shop 224
Stumpp, Emil. Indicating hardening temperature by salt..... 497
Swenson, L. F. Bonus for the ambitious 259
Compulsory membership in the mutual aid 621
Foremen and the wage bonus..... 878
Friendliness in business..... 9
Making a manager out of a foreman.. 331
Mottoes in the shop..... 916
New drills and old men..... 841
Paying for dependability..... 337
Pensions or leaky payrolls?..... 984
Raising the working efficiency..... 487
Should special work be segregated?.. 908
Should the workman share responsibility? 526
Upsetting production schedules..... 214
Using blind ads.—Discussion..... 735
Weights or round steel bars..... 979
What you do, or what you get done.. 53
When personal tools are damaged....1028
Who should do the estimating?..... 404
Who should do the firing?..... 870

TANDY, RONALD L. Who should do the estimating? 613
Tangerman, E. J. Machine shop extraordinary to the "Queen of the Seas" *799
Tangerman, Wm. J. Stripper for multiple punch *884
Tenney, H. W. Spinning spheres for man-made lighting *359
Thacker, F. A. Friendliness in business... 175
Thomas, Edwin W. Safety campaign that achieved results 217
Thomas, John. Cutting a double-thread wormwheel with a single-thread hob.—Discussion 776
Tingley, Edw. H. Compulsory membership in the mutual aid..... 185
Ethics of making a change..... 769
Keeping machines on the job..... 991
Why conference, anyway?..... 695
Tomney, Charles C. Combined core drill and countersink *740
Emergency repair for a threaded arbor. *668
Punch for cloth-inserted packing rings *1000
Towlson, J. T. Accurate drilling of small holes.—Discussion 925
Cutting a thread on a taper..... 348
Keeping a line on tools.—Discussion.. 535
Kinks for the drillers..... 810
Machining from a base line..... 940
Paying for dependability..... 17
Preventing breakage of small taps.—Discussion 68
Spring flexible coupling.—Discussion. 382
Tempering cutting tools..... 248
Tool-economy.—Discussion 1034
Toolholder for high-speed toolbits.... *778
Two drawers in benches.—Discussion. 693
What you do, or what you get done?. 338
Who should do the estimating?..... 759
Tripp, G. W. Does a highly developed system pay? 481
Should estimates be given operatives?. 834
Turton, James G. Chuck for turning valve rings.—Discussion *629
Eating during working hours..... 805
Keeping machines on the job..... 1028
Making tight plug cocks.—Discussion 963
Sales or sincerity?..... 870
To whom should the chief inspector report? 723
Who should do the estimating?..... 404
Tuscany, Arthur J. Important developments in the gray-iron industry.... 415
Twist, F. C. Cross-keys for holding heavy punches.—Discussion *538
Night shift 9

VANDERCOOK, D. D. False tops for drill-press tables *193
Veit, William A. Games at the noon hour 54
More ways than one..... 186
Via, G. Guy. Training by intention..... *725
Training by intention..... *773
Villiger, Joseph. Improved tool clamp.... *194
Vincent, H. H. Compulsory membership in the mutual aid..... 259
Vogel, E. Robert. Making a temporary stepped mandrel *812

WAGNER, O. C. Off with the old, on with the new..... 1028
Threading small screws..... 537

Page

Wallrodt, Willi. Sales or sincerity?..... 722
Walters, O. S. Boss or advisor?..... 803
Who should do the firing?..... 721
Ware, R. B. Gooseneck tool for the shaper —Discussion 629
Warner, W. E. Care of planer belts..... 946
Detecting cracks in metal articles.... 814
Plating stainless steel..... 884
What you do, or what you get done?..338
Wasbauer, Alfred. Advising employees about their affairs 487
Ethics of making a change..... 299
New drills and old men..... 915
To whom should the chief inspector report? 833
Waterhouse, W. L. What you do, or what you get done?..... 525
Who should do the estimating?..... 482
Watson, William. All-modern equipment produces Allis-Chalmers tractors...*436
Weaver, J. R. Determining the when and why of machine tool replacement..1013
Weed, Harold. Games at the noon hour.. 17
Weimar, E. F. Compulsory membership in the mutual aid..... 338
Wells, Walter. Paired strippers for odd-shaped work 922
Westbrook, M. H. Changes in locomotive shop practice 448
Cutting steam ports in cylinder bushings *273
Wheeler, H. L. Fixture for planing circular grooves *776
Gooseneck holder for the shaper..... *66
Handy stop for planer work..... *271
Mandrel for turning splined gear blanks..... *230
Tool for drilling, reaming and spot facing *628
White, P. H. Hand-operated screw punch.. *195
Hand punch for sheet metal..... *64
Removing bolts by stretching them.. 681
Whitehouse, Charles R. Adapter for holding non-magnetic metals..... *925
Adjustable jig *884
Eating during working hours..... 526
Improvised hot press..... *1035
Keeping machines on the job..... 878
New drills and old men..... 621
Power screwdriver *384
Reaming in the lathe..... *629
Sales or sincerity?..... 870
Should estimates be given operatives? 404
Should special work be segregated?.. 688
Smoking during working hours..... 659
Using blind ads.—Discussion..... 248
What price titles?..... 759
Willey, Chas. H. Assembling fixtures for terminals *311
Assembling small screws and nuts.... *196
Bending fixture for a small part..... *466
Bending and jeweling fixtures..... *777
Bulging and flanging shells..... *623
Chip shields for the turret lathe..... *311
Handy angle irons..... *232
Improvised rubber spring for the drawing press *383
Inexpensive fixture for bending coils.. *924
Knurling tool for use in a turret..... 229
Making flat coils from copper wire... *64
Press tools for ammeter covers..... *192
Press tools for cutting off, piercing and forming *667
Press tools for trimming screw heads.. *421
Rubber used for stripper springs..... *196
Should the workman share responsibility? 659
Simple tapping fixture..... *347
Slotting fixture *998
Specifications for customers' orders... 619
Temporary tool for notching and bending *421
Tool economy *421
Tool for bending ears on clamps..... 962
What you do, or what you get done?. 487
Who should be laid off first?..... 299
Williams, C. G. Accuracy and speed in detailing.—Discussion 922
Should price or payroll be cut?..... 723
Williams, Whiting. What if the Soviet's machine gods fall down?..... *321
Wilson, George. Ball with two grooves at right angles *921
Improvised fixture for boring piston-pin holes *311
1930 looks at 1880..... 995
Wilson, Wilbur C. Games at the noon hour 186
Woffington, L. J. Equipment replacement in slack periods..... 404
Fitting the older worker for his job.. 365
Learning from the small shop..... 487
Making a manager out of a foreman.. 687
Off with the old, on with the new.... 804
Too much co-operation..... 732
What price titles?..... 869
What you do, or what you get done?. 260
Who should do the estimating?..... 518
Woods, Geo. R. Assaying the export market *283
Wormwood, A. J. Ammonia-treated gage steel 452
Wright, D. C. Night shift..... 213
Ratio of raw material to production.. 329
Should special work be segregated?.. 797

YEOMAN, I. F. Drill speeding attachment *849

ZEEBROECK, V. VAN. Half turn screws for holding work.—Discussion..... *274

(*) Illustrated (‡) Diagram (ed) Editorial